


OREGON CORNER RESTORATION FORM

CORNER No. 20

Section 27 Township 32S Range 7W

County Douglas Date March, 2002

Corner Designation




- Condition Report Only
- Not Found
- Renewed
- Unrecorded
- Surveyed In
- Referenced Out

Previous Renewals/Surveys, etc. Corner not previously set.

Monument(s) & Accessories ~~Found~~: (Condition and Source)
I set a 3/4" x 40" Iron Rod ^{set} with a 2 1/2" Alum. Cap, from which a:
10" D. Fir BT, I scribed "PCBT", bears S 60° E, 28.5 feet.
12" Madrone BT, I bark scribed "PCBT", bears N 3° E,
14.2 feet.
6 Foot Steel fence post bears North, 10 feet.

Monument Detail

Sketch



FILED
 Date: 3/27/2002 By: X
 This survey consists of:
 Map: M137-35
 Narrative:
 Corner Rpt: 65/42-11-11-39

DOUGLAS COUNTY SURVEYOR

Monument Set (Procedures and Description)

New Accessories

Location & Comments

Surveyor's Seal

Compass Declination 20°E
 Firm/Agency Shaner Engineering
 Address P.O. Box 1430
Roseburg, Oregon 97470
 Party Chief B. Shaner
 Notes " "
 Witness Ben Schneider

REGISTERED
 PROFESSIONAL
 LAND SURVEYOR

Bruce A. Shaner
 OREGON
 OCT. 4, 1987
 BRUCE A. SHANER
 430

Renews June 30,
 C.S. File No 65/42-30 ... 2002