

OREGON CORNER RESTORATION FORM

Section 36 Township 19 South, Range 9 West
County Douglas Date 1 May 2012

FILED
Date: 5/2/2012 By: JC
This survey consists of:
Map: _____
Narrative: _____
Corner Rpt. CS 65/76-52

DOUGLAS COUNTY
SURVEYOR

Corner Description

NE1/16
Section 36

- Condition Report Only
- Not Found
- Renewed
- Unrecorded
- Surveyed In
- Referenced Out

Previous Renewals / Surveys, etc.

5/8" Rebar set in 1977 administrative survey by the Coos Bay, BLM office.
No bearing trees were scribed

Monument (s) & Accessories Found: (Condition and Source)

Found - 5/8" Rebar set in 1977 administrative survey by the Coos Bay BLM office.
No accessories in evidence.

Monument Detail

Sketch

Monument Set (Procedures and Description)

None

New Accessories

12" D. Fir bears S 7° E 9.4 ft. blazed, scribed, NE1/16 S36 BT
12" D. Fir bears S 71° W 25.1 ft. blazed, scribed, NE1/16 S36 BT

Location & Comments

Corner has steel post adjacent to it.
All BT's have red painted bands and yellow tags.

Compass Declination 16° East
Firm/Agency Northwest Land Surveying Inc.
Address P.O. Box 2827 Florence, OR 97439
Party Chief Ron Rice
Notes _____
Witness Jason Collver

Surveyor's Seal



RENEWS: 12-31-2012

C.S. File No 65/76-52