

FILED

Date: 8/28/2012 By: JC

This survey consists of:
~~Map:~~ This corner report was downloaded
from the Jackson Co. Surveyor's
~~Narrative:~~ Office web site 8/28/2012

Corner Rpt: C.S. 65/77-24

FIRST RE-ESTABLISHMENT

GCDB 140300

**DOUGLAS COUNTY
SURVEYOR**

Quarter corner common to Sections 19 and 30, Township 30 South, Range 3 East, W.M.

Found at the corner position, exposed 3 ins., the 1 in. diam. galv. iron pipe with a 2½ ins. diam. brass cap set by the GLO in 1928, marked:

S19
¼—
S30
1928

Bearing trees recorded by Herbert Raymond of the GLO in 1928 found with healed blazes and measured to center at base:

- W. fir, now 55 ins. diam. brs. record; N 25°E, 31.0 ft.
- S. fir, now 25 ins. diam. brs. S 14° E, 16.5 ft. Record; S 13° E.

Mark new bearing trees "CS" "BT" and take measurements to center of trees at lower blaze:

- W. fir 10 ins. diam. brs. N 52° W, 17.0 ft.
- S. fir 10 ins. diam. brs. S 28¼° W, 9.8 ft.

Corner lies approx. 2000 ft. westerly, then northerly along "Golden Stairs" Trail No. 23, from switchback in spur road to the county line; then, easterly approx. 300 ft.

July 28, 2010

H. Durkee

S. Fein

Kerry K. Bradshaw

Jackson County Surveyor

P. – 166

V. – 15°30'