

FILED

OREGON CORNER RESTORATION FORM

Date: 9-18-2012 By: JC

This survey consists of:

Map: _____

Narrative: _____

Corner Rpt: C.S. 65/77-33

DOUGLAS COUNTY
SURVEYOR

Section 32 Township 24 South, Range 2 West
County Douglas Date 6 September 2012

Corner Description

E 1/4 Corner

Section 32

- Condition Report Only
- Not Found
- Renewed
- Unrecorded
- Surveyed In
- Referenced Out

Previous Renewals / Surveys, etc.

Monument (s) & Accessories Found: (Condition and Source)

Found 1" dia. Iron post with BLM brass cap dated 1951

A Cedar, 13" dia., bears S.82¼°E., 28.4 ft., mkd: ¼ S33 BT.
(Found 13" dia.x 5' high Cedar stump with scribing visible)

A yew, 16" dia., bears N.56¼°W., 17.8 ft., mkd: ¼ S32 BT.
(Found 17" Yew with scribing visible)

Monument Detail

Sketch

Monument Set (Procedures and Description)

None

New Accessories

16" D. Fir bears N76°W 10.3 ft., scribed 1/4 S32 BT

14" Hemlock bears N 68°E 4.6 ft., scribed 1/4 S33 BT

19" D. Fir bears S20°E 22.9 ft., scribed 1/4 S33 BT

Location & Comments

Corner has steel post _____ Compass Declination 16° East

adjacent to it. _____ Firm/Agency Northwest Land

All BT's have red painted _____ Surveying Inc.

bands and yellow tags. _____ Address P.O. Box 2827
_____ Florence, OR 97439

_____ Party Chief Ron Rice

_____ Notes _____

_____ Witness Jason Collver

Surveyor's Seal



RENEWS: 12-31-2012

C.S. FILE 65/77-33