

Index

CORNER RECORD (SEARCH)

File No. L-21 PROJ. NO. ELK CORNER 1/4  
 TOWNS. 32 S RANGE 2 W R.D. TILLER COUNTY DOUGLAS GCDB# 600440  
 MERID. WM FOREST UMPQUA STATE OREGON

<p><b>CORNER DIAGRAM</b></p> <p>N ↑ MONUMENT FOUND   DISTURBED   SEE REMARKS    </p>	<p><b>DESCRIBE CORNER MONUMENT FOUND</b></p> <p>FOUND 2-1/2" DCSO BRASS CAP ON 1-1/4" IRON PIPE, PUSHED BY CAT AND LEANING NORTHEAST ABOVE MOUND OF STONE AND BELOW SLASH PILE.</p> <p><b>DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND</b></p> <table border="1" style="width:100%; border-collapse: collapse;"> <thead> <tr> <th>DIA</th> <th>TYPE</th> <th>BEARS</th> <th>DIST</th> <th>FACE/MARKINGS</th> </tr> </thead> <tbody> <tr> <td>12"</td> <td>YEW</td> <td>(N89E)</td> <td>(32.0 FT)</td> <td>SCRIBE ON PART. HEALED DOUBLE BLAZE</td> </tr> <tr> <td>2"</td> <td>W-FIR</td> <td>(S43W)</td> <td>(76.5 FT)</td> <td>HEALED DOUBLE BLAZE</td> </tr> </tbody> </table>	DIA	TYPE	BEARS	DIST	FACE/MARKINGS	12"	YEW	(N89E)	(32.0 FT)	SCRIBE ON PART. HEALED DOUBLE BLAZE	2"	W-FIR	(S43W)	(76.5 FT)	HEALED DOUBLE BLAZE
DIA	TYPE	BEARS	DIST	FACE/MARKINGS												
12"	YEW	(N89E)	(32.0 FT)	SCRIBE ON PART. HEALED DOUBLE BLAZE												
2"	W-FIR	(S43W)	(76.5 FT)	HEALED DOUBLE BLAZE												
<p><b>PHOTO IDENTIFICATION DATA</b></p> <p>Photo No. _____                  Filed At. _____                  Obj. Ident. _____                  Ident. By _____                  Signature _____</p>	<p style="text-align: center;"><b>REGISTERED PROFESSIONAL LAND SURVEYOR</b></p> <p style="text-align: center;"><i>John Ransom</i></p> <p style="text-align: center;">( ) = RECORD PER 1963 DCSO RECORD</p> <p style="text-align: center;"><b>OREGON</b>                  JULY 21, 1902                  JOHN C. RANSOM</p>															
<p><b>PLANE COORDINATE POSITION DATA</b></p> <p>State _____ Zone _____                  North _____                  West _____                  Estab. By _____</p>	<p><b>DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER</b></p> <p>CORNER FALLS ON NORTH SLOPE AND AT CORNER OF PRIVATE CLEAR CUT IN THREE DIRECTIONS, TAKE FOREST ROAD 1616-140 TO JUST SOUTH OF CORNER, ONLY ONE LARGE TREE REMAINS ON PRIVATE HERE IS THE BT, FOLLOW SMALL SPUR ROAD TO CORNER, CORNER FALLS IN SOUTH CUT BANK OF SAID SPUR.</p>															

Signature \_\_\_\_\_ Title \_\_\_\_\_ Division \_\_\_\_\_ Headquarters \_\_\_\_\_ Date \_\_\_\_\_ 7100-52 (3/68)

CORNER RECORD (PERPETUATION)

<p><b>MONUMENT : DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT</b></p> <p>FOUND MONUMENT BURRIED IN A PILE OF SLASH PUSHED ONTO CORNER BY CAT, CUT OUT SLASH OVER CORNER POSITION AND FIND MONUMENT LEANING HEAVILY IN THE DIRECTION OF CAT WORK. CORNER BELIEVED TO HAVE BEEN PUSHED OUT OF POSITION, NO WORK DONE TO STRAIGHTEN MONUMENT. "LAND LINE" FLAGGING TIED ON MONUMENT AND GUARD POSTS</p>	<p><b>ACCESSORIES : DESCRIBE NEW BT's WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE</b></p> <p>NO NEW ACCESSORIES ADDED                  NEW NAILS IN BT TAGS AND PAINTED FACES &amp; 6 INCH BAND AT HEAD HEIGHT</p>
<p>DONE BY: <u>Jonathan Drew</u> TITLE <u>LSIT</u> DATE <u>9/10/2013</u> PLS NO./AGENCY/STATE <u>JOHN RANSOM, PLS2561</u></p> <p>Certified Cor. Record Prepared? <u>NO</u> Filed At: _____ DATE _____</p>	<p style="text-align: center;"><b>REMARKS</b></p> <p>PROPERTY LINE MAINTINED NORTH .75 MILES</p> <p>CORNER MONUMENT NO LONGER IN CORRECT POSITION, WORK NEEDED TO CORRECT DAMAGE DONE BY PRIVATE LOGGING</p>

Index File No L-21 T. 32 S R. 2 W M. WM Proj No. ELK Cor. 1/4

14 5.14.13

C.S. File No 65/85-33