



**BT6**  
**COUNTY SURVEYOR'S RECORD**  
 OF  
**RE-ESTABLISHED GOVERNMENT CORNERS**

437

GROSSENBACH ENGINEERS/E00406864JB

Decl. Compass 17° E	Mo. March 18	Day 2015	Year	No.	Book	Page
Old Monument	Powell 1967				Book 12,	Pg. 008
<p>Found 2 1/2" brass cap on a 1 1/4" o.d. iron pipe, 0.5' tall, in good condition and solid in the ground. BCIP was found under a 36" diameter Douglas Fir uprooted snag. We cut a notch in the snag and straightened the monument into the newly cut out area. Monument leans slightly to the East on the North side of the uproot. We set a Douglas Fir post 1' North and paint the top in blue.</p>						
Old BT	Simon 1993				Vol. 51, Pg.	19554
<p>Found a 13" Douglas Fir stump, N56°30'W, 15.69' (N59°30'W-16.17' rec.) to heart center. We chop out face and find scribes. We paint the face and the top of the stump in blue. <b>GOOD CONDITION</b></p>						
Old BT	Simon 1993				Vol. 51, Pg.	19554
<p>Found a 12" Douglas Fir stump, S48°W, 13.87' (S47°30'W-14.85' rec.) to heart center. We chop out face and find scribes. We paint the face and the top of the stump in blue. <b>GOOD CONDITION</b></p>						
Old BT	Simon 1993				Vol. 51, Pg.	19554
<p>Found a 10" White Cedar stump, S48°E, 13.06' (S49°45'E-12.54' rec.) to heart center. We saw off the top and find scribes. We paint the top of the stump in blue. <b>GOOD CONDITION</b></p>						
<p><b>New BO</b>          A 36" White Cedar stump 2.5' tall, N19°30'E, 36.03' to a spike and Coos County washer driven in at heart center. We chop an "X" in the face and paint the "X" and the top of the stump in blue and attach a yellow Coos County tag.</p>						
<p><b>Present:</b>          Matthew Martin          Bill Hales</p>						
<p><b>FILED</b></p>						
<p>Date: 4-28-2015 By: <u>X</u>          This survey consists of:          Map:          Narrative:          Corner Rpt: <u>CS 65/87-61</u></p>						
<p><b>DOUGLAS COUNTY SURVEYOR</b></p>						
<p>100300 T31-9</p>						
<p>C.S. FILE <u>65/87-61</u></p>						