

FILED

Date: 7/9/2019 By: SC

This survey consists of:

Map: _____

Narrative: _____

Corner Rpt: CS 65/102-62

OREGON CORNER RESTORATION FORM

SECTION 4 **TOWNSHIP 22S** **RANGE 11W, WM**

DOUGLAS COUNTY
SURVEYOR

Corner Designation

SW1/16 CORNER SECTION 4

Previous Renewals / Surveys, etc.:

M74-65

- Condition Report Only
- Not Found
- Renewed
- Unrecorded
- Surveyed in
- Referenced Out

Monument Detail Sketch

Monument Found or Set (Procedures and Description)

FOUND MONUMENT:

A 5/8" IRON ROD, PER M74-65

FOUND BT:

A ROTTEN 14" FIR STUMP WITH NO VISIBLE MARKS BEARS N45°W 21.8'.

New Accessories

NEW BT'S MARKED:

A 10" FIR, FACE SCRIBED "SW1/16 S4 BT" WITH X-CHOP AND TAG BEARS S55°W 8.90' TO A SPIKE AT SIDE CENTER.

A 15" FIR, FACE SCRIBED "SW1/16 S4 BT" WITH X-CHOP AND TAG BEARS N10°W 19.9' TO A SPIKE AT SIDE CENTER.

Locations & Comments

LAT. AND LONG. PER GARMIN ETREX HAND HELD GPS

N: 43°40'53.7" W: 124°01'28.7"

DATE 5/24/19

Compass Declination used on hand compass 18° EAST

Firm / Agency: Estabrook Land Surveying Inc.

Address: PO BOX 574, Lakeside, OR 97449

Party Chief: Pat Coy

Notes:

Witness: John Rondeau and Ray Banks

Surveyors Seal

REGISTERED
PROFESSIONAL
LAND SURVEYOR



OREGON
JUNE 30, 1995
JERRY LEE ESTABROOK
2703

EXPIRES 12/31/19

C.S. FILE 65/102-62

320620