

FILED

Date: 7/9/2019 By: JC

This survey consists of:

Map: _____

Narrative: _____
Corner Rpt: CS 65/102-64

OREGON CORNER RESTORATION FORM

SECTION 4 TOWNSHIP 22S RANGE 11W, WM

DOUGLAS COUNTY
SURVEYOR

Corner Designation


CS1/16 CORNER SECTION 4

Previous Renewals / Surveys, etc.:

DCSO RECORDS VOL. 53 PAGE 20227

- Condition Report Only
- Not Found
- Renewed
- Unrecorded
- Surveyed in
- Referenced Out

Monument Detail Sketch



Monument Found or Set (Procedures and Description)

FOUND MONUMENT:

A 2 1/2" STAINLESS STEEL PIPE WITH BRASS CAP MARKED "C S1/16 C S4 1992", PER DCSO RECORDS VOL. 53 PAGE 20227.

FOUND BT'S:

A ROTTEN 10" FIR STUMP WITH HEALED FACE BEARS S38°E 47.85'.

A ROTTEN 18" FIR STUMP WITH VISIBLE SCRIBE IN FACE BEARS N55°W 13.53'.

New Accessories

NEW BT'S MARKED:

A 9" FIR, FACE SCRIBED "CS1/16 S4 BT" WITH X-CHOP AND TAG BEARS N43°E 16.4' TO A SPIKE AT SIDE CENTER.

A 16" FIR, FACE SCRIBED "CS1/16 S4 BT" WITH X-CHOP AND TAG BEARS N12°W 21.5' TO A SPIKE AT SIDE CENTER.

Locations & Comments

LAT. AND LONG. PER GARMIN ETREX HAND HELD GPS
N: 43°40'53.7" W: 124°01'10.4"

DATE 5/24/19

Compass Declination used on hand compass 18° EAST

Firm / Agency: Estabrook Land Surveying Inc.

Address: PO BOX 574, Lakeside, OR 97449

Party Chief: Pat Coy

Notes:

Witness: John Rondeau and Ray Banks

Surveyors Seal

REGISTERED
PROFESSIONAL
LAND SURVEYOR

OREGON
JUNE 30, 1985
JERRY LEE ESTABROOK
2703

EXPIRES 12/31/19

340 620

C.S. FILE 65/102-64