

GOVERNMENT CORNER RESTORATION FORM

Date: 6/2/1998 By: X

Township 28S Range 7W Sec. 6

County DOUGLAS

This survey consists of:

State OR


Date 5-28-98

No. \_\_\_\_\_

Narrative: \_\_\_\_\_

Corner Rpt: 6612-42

Corner Designation



DOUGLAS COUNTY

Condition Report Only

Not Found

Renewed

Unrecorded

Surveyed In

Referenced Out

MONUMENT DETAIL

Previous Renewals 1929660, 19305 + 1961 DC50

Monument(s) Found: (Condition and Source)

2 1/2" DIA BRASS CAP ON A 2" DIA IRON PIPE, PROTRUDES 15" ABOVE A MOUND OF SAND STONE, 1924

U.S. GENERAL LAND

PROPERLY MARKED

OFFICE SURVEY

Accessories Found:

26" NOW 27" DIA 2 FT HIGH ROTTEN D. FIR STUMP WITH SCRIBING VISIBLE "56 BT BEARS S48°W, 56.8 FT (AGREES WITH 1929 RNC.) 1929

12" NOW 20" DIA D. FIR WITH A FULLY HEALED DOUBLE BLAZE, BEARS N55 1/2°W, 35.5 FT (RNC. N53 1/2°W, 35.5 FT) 1961

5" NOW 15" DIA D. FIR WITH A FULLY HEALED DOUBLE BLAZE, BEARS S13°W, 15.7 FT (AGREES WITH RNC.) 1961

