

GOVERNMENT CORNER RESTORATION FORM

Date: 5/24/1999 By: JC

This survey consists of:

Township 27S Range 7W Sec. 2 County DOUGLAS Map: _____

State OR Date 2-3-1998 No. 043020.012 Narrative: _____

Corner Rpt: 66/8-26

Corner Designation

DOUGLAS COUNTY SURVEYOR

NW EXT
DLC 43

- ____ Condition Report Only
- ____ Not Found
- Renewed
- ____ Unrecorded
- ____ Surveyed In
- ____ Referenced Out

M 48-75

Previous Renewals 1929, 1957, 1972 AND 1977 OCSO

MONUMENT DETAIL

Monument(s) Found: (Condition and Source)

5/8" IRON ROD FOUND
7" BELOW GRAVEL ROAD SURFACE, 1977

N/A

Accessories Found:

10" Now 24" ROTTEN OAK STUMP, BEARS
S 63 3/2° E, 43.6 FT (AGREES WITH REC.) OBT

6" Now 12" DIA 2 FT HIGH W/OAK STUMP
WITH A FULLY HEALED BLAZE BEARS
S 60° E, 75.6 FT (AGREES WITH REC.) 1957

1" L.P. IRON PIPE FOUND 7" BELOW ROAD
SURFACE SW COR DLC 44" BEARS
S 87 3/4° E, 68.4 FT (AGREES WITH REC.)
M 48-75

