

FILED

GOVERNMENT CORNER RESTORATION FORM

Date: 10/14/1999 By: JC
This survey consists of:
Map: _____

Township 29S Range 5W Sec. 29 County DOUGLAS

State OK Date 8-24-99 No. 240200.019

Narrative: _____
Corner Rpt: 666/12-15

Corner Designation

$\frac{1}{4} \frac{S29}{S32}$

DOUGLAS COUNTY

Condition Surveyor Only

Not Found

Renewed

Unrecorded

Surveyed In

Referenced Out

Previous Renewals 1947 VOL 7 P 35, 1990 PCS 0

MONUMENT DETAIL

Monument(s) Found: (Condition and Source)

A 3/4" I.P. PER 1947 IS
FOUND AT THE INTERSECTION OF
NEWER FENCES RUNNING NORTH
AND EAST, APPROX. 30 FT
EAST OF THIS FENCE
CORNER IS AN OLD PARTIALLY
DOWN N-S FENCE LINE.

NONE

THE 1947 I.P. WAS SET
AT A PROPORTIONED POSITIONED
BASED ON THE SW CORNER
POSITION OF SECTION 29.
AN ORIGINAL BT WAS FOUND
FOR THE SW COR OF SEC 29
APPROX 300 FT NORTH OF
ITS 1947 POSITION,

Accessories Found:

NO ORIG. BT'S FOUND

