

FILED NOV 17 1999

225 R8W 1/4 S10 | S11

11-8-1999 RANDALL W SMITH, STEPHEN J FLASE

FD 1967 BLM 30" LONG BRASS

W/ IRON PIPE 4"

BELOW GROUND, OUT OF

POSITION IN SLID OUT BANK.

POSITION OF CORNER DETERMINED

BY DIST'S + BRG'S TAKEN TO BO'S

AND BT'S. 1/2" ANGLE IRON

5 FT LONG IS SET AT CORNER

PORTRUDES 10" OUT OF CREEK

BANK.

36" NOW 36" DIA. 6 FT HIGH D. FIR STUMP

NO SCRIBING OR BLAZES VISIBLE

BEARS S54°E 118.8 FT 0BT

20" NOW 34" DIA D. FIR WITH A FULLY

HEALED DOUBLE BLAZE BEARS

S10 1/2°E, 58.5 FT 1962

18" NOW 31" DIA. D. FIR WITH A FULLY

HEALED DOUBLE BLAZE BEARS

S14°N, 73.5 FT 1962

5/8" I.R. WITH ALUM CAP BO 1

BEARS N23 1/2°E, 92.8 FT 1989

5/8" I.R. WITH ALUM CAP BO 2

BEARS N66 1/2°W, 125.2 FT 1989

ON BACK G.S. FILE NO. 66/12-41

J. L. BARLING COP
TACOMA, WASH. U.S.

"Put in the Rain"
WEATHERPROOF

No. 312

FD 5/8" I.R BEARS
N 41 1/2° E , 5.1 FT

SET 1967 BLM BRASS
CAP / IRON PIPE NORTH
14.0 FT . 1 FT SOUTH
OF A NEW E-W FENCE
LINE PROTRUDE 6"
ABOVE GROUND MARKS
ADDED "DCSO 1999 SOUTH
14 FT TO COR"

U.S. DEPT OF THE INTERIOR

1/4

DCSO
1999

S10/S11

SOUTH 14 FT
T22S R8W
TO 1967 COR

BUR. OF LAND MANAGEMENT