

FILED FEB 8 2000

T 27 S R 4 W 7-3-00

533 534

RANDALL W SMITH

54 53

T 28 S

STEPHEN J FLAUSK

FD 1958 BLM BRASS CAP/IRON PIPE

PROTRUDS 6" OUT OF GROUND

CORNER LIES AT INTERSECTION OF

N-S AND WEST RUNNING ~~FOUR~~ LINES

14" NOW ROTTED TO GROUND OR EVIDENCE

OF OLD BLAZES, NO SCRIBING FOUND

BEARS N 42° W, 71.3 FT OBT

15" NOW ROTTED DOWN MADRONE NO

BLAZES OR SCRIBING FOUND BEARS

N 18° E, 85.8 FT OBT

NE AND SW BT'S FROM 1958 BLM

SURVEY NOW GONE

5" NOW 16" DIA. D. FIR WITH A FULLY

HEALED SINGLE BLAZE, BEARS

S 71 1/4° W, 96.5 FT (REC S 69 1/4° W,

90.4 FT) 1958

13" NOW 24" DIA. D. FIR WITH A FULLY

HEALED SINGLE BLAZE, BEARS N 12 3/4° W

72.6 FT 1958

10" NOW 24" DIA D. FIR WITH A FULLY HEALED

SINGLE BLAZE, BEARS S 56 1/2° W, 79.2 FT

(REC. S 58° W, 79.2 FT) 1974

400100

SEE BACK CS. FILE NO. 66/14-5

NEW

14" DIA DIFIR DOUBLE BLAZED
AND SCRIBED "T28S R4W
S3CSBT" BEARS S21 1/2° E,
16.3 FT

CORNER LIES 5 FT NORTH
OF A SMALL SEASONAL
CREEK IN A SHALLOW DRAW

NO GRANITE + QUARTZ OUTCROPPING
AS NOTED IN 1958 VISIBLE
AT CORNER

66/14-15