

FILED JUL 21 2000

T305 RGW | NW
DLC 39 7-11-00

RANDALL W SMITH

STEPHEN J FLAUSÉ

FD STONE "C" VISIBLE ON
EAST EDGE PROTRUDES 3" ABOVE
GROUND (1924)

1963 DCSO BRASS CAP ON AN
IRON PIPE, PROTRUDES 7"
ABOVE GROUND. BC/IP
IS ALONG NORTH EDGE OF
STONE (SOUTH 0.5 FT TO STONE)
NO QBT'S FD
FROM BC/IP

10" NOW DOUBLE TRUNKED, 17" W. OAK
SOUTH EAST TRUNK HAS A HEALED
BLAZE CENTER OF ROOT CROWN
OF SE TRUNK BEARS S51°E,
45.5 FT (REL S49½°E 45.5) (1924)

10" NOW 20" DIA W. OAK WITH
A FULLY HEALED DOUBLE BLAZE
BEARS S51°E, 39.0 FT (REL
S52½°W, 39.0 FT) (1924)
NEW

12" DIA MADRONE DOUBLE BLAZED
AND SCRIBED "NW DLC 39 CS 13"
BEARS N66°E 46.8 FT
(ON BACK) C.S. File No. 66/16-21

NOT FOUND DLC 39

CORNERS IN T305 RW

ESE 039060

INT L 039050 (Int-SE)

SSE 039040

SW 039030

CS 66/16-21