

9-28-00

FILED OCT 5

2000

21# 400440

T77SK4W 1/4 516 | 515

RANDALL WISNITH, STEPHEN J FLAUS

FD 1958 DCSO BRASS CAP

IRON PIPE PROTRUDS 12"

ABOVE GROUND.

- 10" NOW 12" DIA 8 FT HIGH

ROTTED OAK SNAG BEAMS

N 25° E 13.0 FT (OBT)

- 23" NOW 22" DIA DOWN

AND ROTTED D. FIR ROOT

HOLD BEAMS S 76° E 13.0 FT (1958)

- 20" NOW 20" DIA ROTTED

D. FIR STUMP BEAMS

S 76° W 18.0 FT (1958)

- 6" NOW 10" DIA MADRONE

WITH FAINT LOW BARK

SCRIBING "1/4 15 CS BT" WE

RESCRIBE HIGHER ON A SINGLE

BLAZE "1/4 515 CS BT" BEAMS AS

S 69° E, 48.0 FT (1984)

ON BACK C.S. File No. U6/16

DIETZEN NO. 385-5

4" NOW 11" DIA MADRONA

NO BARK SCRIBING

VISIBLE NE PRESCRIBED

"Y4 SIG CS BT" ON A

DOUBLE BLAZE, BEARS

S72½°W, 35.9 FT (1964)

NEW

6" DIA B. OAK DOUBLE

BLAZED AND SCRIBED

"X CS BT" BEARS N26°E

14.0 FT THIS TREE IS

AT A 3WAY FENCE CORNER

WITH FENCE LINE RUNNING

N-S AND EAST.

6" DIA MADRONA DOUBLE

BLAZED AND SCRIBED "Y4

SIG CS BT" BEARS

N40°W, 28.5 FT

(NO DESCENT TREES AROUND CORNER)

CS 66/16-48  
96-91/9957