

1-29-01

T285

GPSR012920A

$\frac{1}{4}$   $\frac{531}{56}$   
- 295

R  
W

RANDALL W SMITH

STEPHEN J FLAUS

FD 2 1/2" DIA. BADLY BENT I.P. (1923)  
AND 1" DIA. BADLY BENT IRON PIPE BRASS,  
CAP FD ALONG SIDE (1929)

5" ASH FROM REN #1 SOURCE UNKNOWN  
PROBABLE 12" ASH IN 1961 NOW

25" DIA ASH WITH A FULLY HOLED  
SINGLE BLAZED BEARS N 9 1/2° W

11.5 FT

5" W. OAK PROBABLE 1961 BT NOW

18" DIA W. OAK SCAR NOT VISIBLE  
BEARS S 70° W 25.3 FT (1961

RECORD S 70° W, NO DIST).

NO OTHER BT'S FOUND

NOW 17" DIA W. OAK DOUBLE

BLAZED AND SCRIBED "1/4 S 6 C S BT"

BEARS S 67° E, 33.6 FT

16" DIA ASH DOUBLE

BLAZED AND SCRIBED "1/4 S 31 C S BT"

BEARS N 23 1/2° E, 57.3 FT

INTERSECTION OF STATE HWY 92  
AND BENEDICT RD (COORD # 141)

BEARS EAST 85 FT

(ON BACK)

C.S. File No. 66/19-20

J. L. DARLING CORP  
TACOMA WASH. U.S.A.

"Rite in the Rain"  
WEATHER RESISTANT

FILED FEB 21 2001

No. 302

SET  $2\frac{3}{8}$ " DIA. BRASS CAP  
ON A  $1\frac{7}{8}$ " O.D. BY 32" LONG  
IRON PIPE AT PLUMB POSITION  
OF FOUND I.P.'S PROTRUDES  
4" OUT OF GROUND OLD  
I.P.'S SET ALONG SIDE NEW  
BL/I.P. BOTH 36" LONG

DOUGLAS COUNTY SURVEYORS OFFICE

T 28 S

$\frac{1}{4}$	<u>S 31</u>	R
	S 6	7 W

T 29 S

2001

66/19-20