

2-1-01

FILED FEB 21 2001

T288 RBW 1/4

525
536

RANDALL W. SMITH STEPHEN J FLAUSCH

FD 1969 DCSD BRASS CAP IRON

PIPE, PROTRUDES 7' OUT OF
GROUND. IN OPEN FIELD

56 FT NORTH OF A E-W FENCE
LINE. NOTE THIS CORNER

SET BY PROPORTIONING IN 1969

I BELIEVE OBT'S ARE STANDING

WITH BLAZES GONE. 1969 CORNER

IN REASONABLE POSITION FOR

ORIG CORNER.

20" NOW 39" DIA W. OAK PREVIOUSLY

OPENED WITH A POTTER CENTER.

TREE IS ALIVE W/ SINGLE BLAZE

5 FT ABOVE GROUND " 1/4 525 BT "

BEARS N 84 1/4° E, 724.5 FT.

(ORIG. REC. N 84 1/4° E, 721.0 FT) OBT?

18" NOW 29" DIA W. OAK PREVIOUSLY

OPENED NO MARKS VISIBLE. W/ S

SINGLE BLAZE 5 FT ABOVE GROUND

" 1/4 S 36 BT " BEARS S 89 3/4° W,

654.6 FT (ORIG. REC. S 89 1/4° W,

656.7 FT) OBT?

(ON BACK)

C.S. FILE NO. 66/19-25

J. L. DARLING CORP.
TACOMA WASH. U.S.A.

"Set in the Rain"
WEATHERPROOF

No. 302

1969 FOUND B. OAK BT NOW
29" DIA. WITH A FULLY HEALED
DOUBLE BLAZE, BEARS $53\frac{1}{2}^{\circ}E$,
369.7 FT.

METAL READING TAPE NORTH
10 FT FROM BC/IP 1969 I.R.

1924 GLO BC/IP INT SE COR,
DLC 37 AP 5 BEARS
 $N 89\frac{3}{4}^{\circ}E$, 826.3 FT (REC.
PER 1969 $N 89^{\circ}09'40''E$, 826.99 FT

NOTE UNRECORDED GLO
BC/IP'S FOUND IN AREA
SEE RENEWALS OF DLC 37
I BELIEVE 1924 GLO SURVEYS
OPENED OBT'S AND FOUND
CORNER. SOUTH ONLY B. OAK BT
PROBABLE 1924 RENEWAL TREE
NO GLO BC/IP FOUND

66/19-25