

5-15-01

T 26 S

R 3 W $\frac{1}{4}$ 532

55
T 27 S

FILED MAY 21 2001

RANDALL W SMITH STEPHEN J FLAUSCH
FD 1950 DCSO BENT BC/IP
PROTRUDES 3" ABOVE GROUND BENT
5" NW OF PLUMB POSITIONS.
PLUMB POSITION REFERENCED
BC/IP REMOVED AND STRAIGHTENED
FLANGES IN GOOD SHAPE IP
MEASURES 36" LONG,

COUNTY SURVEYOR
COR

$\frac{1}{4}$ T 26 R 3
532
55

T 27 R 3
OFFICE

NO BT'S FOUND POSSIBLE
ROOT HOLE OF 1950 NW BT
(REL N60W 19.1 FT)

BRASS CAP IRON PIPE RETURNED
TO PLUMB POSITION, PROTRUDES
3" ABOVE GROUND.

ON BITCH

C.S. File No. 66/21-18

NEW

13" DIA. D. FIR DOUBLE BLAZED
AND SCRIBED "Y455CS BT"
BEARS S21°E, 33.7 FT

6" DIA. D. FIR DOUBLE BLAZED
AND SCRIBED "Y455CS BT"
BEARS S5°W, 42.3 FT

7" DIA. D. FIR DOUBLE BLAZED
AND SCRIBED "Y4532CS BT"
BEARS N13°E, 67.9 FT

7" DIA. W. OAK DOUBLE BLAZED
AND SCRIBED "Y4532CS BT"
BEARS N29°W, 64.0 FT

COMPASS DECL. 17³/₄°E

66/21-18