

T285 R8W WSW COR DLC 40

RANDALL W SMITH

JOHN A. PIKE

FD 1984 BLM BRASS CAP/IRON  
PIPE, PROTRUSION 5" ABOVE  
GROUND. 1951 3/4" IRON PIPE  
ALONG EASTERN EDGE OF BLM  
BLP. FLUSH WITH GROUND

10" MADRONE NOW ROOT HOLE  
BEARS N55°E, 15.2 FT OBE?

BOTH 1951 BT'S NOW GONE

10" NOW 19" DIA 6 FT D. FIR  
STUMP WITH A FULLY HEALED  
DOUBLE BLAZE, BEARS N37 1/2°W,  
42.2 FT (1966)

10" NOW 24" DIA 1 FT HIGH D. FIR  
STUMP NO BLAZES VISIBLE, BEARS  
N57 1/4°E, 50.8 FT (1966)

NEW

10" DIA W. OAK DOUBLE BLAZED  
AND SCRIBED "WSW DLC 40 CS BT"  
BEARS N18 1/2°E, 7.5 FT

8" DIA W. OAK DOUBLE BLAZED  
AND SCRIBED "WSW DLC 40 CS BT"  
BEARS S70°E, 28.1 FT

8" DIA MADRONE DOUBLE BLAZED AND  
SCRIBED "WSW DLC 40 CS BT" BEARS  
N74 1/2°W, 21.4 FT

COMPASS DECL.

17  $\frac{3}{4}$  40 E