

2-19-01 FILED SEP 28 2001

RANDALL W SMITH  
STEPHEN J FEAUSE

T225 R6W  $\frac{1}{4}$  S12

NO ORIG B.OAK BT'S FOUND

NO MONUMENTS FOUND

FP 30" DIA W.OAK SNAG WITH  
CENTER ROTTED OUT IN AN  
E-W FENCE LINE THIS TREE  
HAS BEEN PREVIOUSLY OPENED  
IN PAST ON SE, NE + W OF TRUNK  
SNAG ALSO HAS OLD LINE  
BLAZES ON W + E TRUNK. NO  
SCRIBING FOUND.

IN 1903 NEW BT'S MARKED  
AT CORNER NO BRG OR DIST.  
GIVEN SEE CS 64/48 PG 7

POSITION OF ABOVE OAK SNAG  
FIT'S REASONABLY WITH ROUGH TIE  
TO STONE MONUMENT SET  
ON ALL 44 LINE INTERSECTION  
WITH SECTION LINE 1903?  
SEE CS 64/48 PG 8

SET  $\frac{5}{8}$ " X 30" LONG IRON ROD  
WITH YELLOW PLASTIC CAP IS SET AT  
CENTER OF SNAG TO PROTECT ITS  
POSITION AS SNAG IS IN POOR SHAPE.

C.S. File No. 66/29-9