

10-10-01

T22 S 126 W

54/53 FILED OCT 24 2001
59/510

RANDALL W SMITH STEPHEN J FLAUSCH

FD 1/2" I.D. IRON PIPE 4"
BELOW GROUND (1914)

ORIG. BT'S LOOKED FOR
NO POSITIVE EVIDENCE FOUND

- 36" NOW ROOT HOLE BEARS
N73°W, 29.7 FT (OBT?)
- 50" NOW LARGE BADLY ROTTED
BURNT D. FIR STUMP, NO
SCRIBING FOUND, BEARS N67 1/2°E,
118 FT (REC N70°E 131.3 FT) (OBT?)
- 50" NOW LARGE 3 1/2 FT HIGH
ROTTED D. FIR STUMP NO SCRIBING
FOUND, BEARS N74°E 118 FT
(REC N70°E, 131.3 FT) (OBT?)
- 30" NOW LARGE BADLY ROTTED
BURNT STUMP, NO SCRIBING FOUND,
BEARS S42 1/2°E, 99.4 (REC S48°E,
97.7 FT) (OBT?)

TO PROTECT POSITION OF
FOUND IRON PIPE WE SET
A 5/8" BY 32" LONG IRON ROD
WITH A DCSO ALUM. CAP

C.S. File No. 66/29-17

No. 302

STAMPED "2001" ALONG SOUTH
EDGE OF FOUND I.P. PROTRUDES
8" ABOVE GROUND.

5" DIA. D. FIR DOUBLE BLAZED AND
SCRIBED "XCS BT" BEARS N82°E,
8.4 FT.

9" DIA. W. OAK DOUBLE BLAZED AND
SCRIBED "XCS BT" BEARS N22°W,
17.2 FT

10" DIA. MAPLE DOUBLE BLAZED AND
SCRIBED "XCS BT" BEARS S59°W,
18.4 FT