

11-7-01 FILED NOV 13 2001 P1 # 038020

T225 R5W NW DLG #38

FD 1980 2 1/2" O.D. BRASS  
CAP/IRON PIPE, PROTRUDES 2"  
OUT OF GROUND MARKED

T225 R5W W.M.

  
D.L.G. 38

R.L.S. 430 1980

1963 HAINES "T" IRON  
ALONG NORTH EDGE OF B.Y.P.  
PROTRUDES 2" OUT OF GROUND.  
CORNER IS AT A 3-WAY  
FENCE CORNER WITH LINES  
RUNNING W'ly, SW'ly  
AND NE'ly

20" OAK NOW ROOT HOLE  
BEARS NS<sup>0</sup>W, 47.5 FT (OBT)  
NOTE 24" DOUBLE TRUNKED D.FIR  
STUMP IN 1980 RENEWAL IS  
NOT ORIG NW BT

16" NOW 18" DIA 6 FT HIGH

D.FIR STUMP WITH A FULLY  
(ON BACK)

C.S. File No. 66/29-23

HEALED DOUBLE BLAZE BEARS  
N 44 1/4° W, 35.5 FT (1948)

24" NOW 25" DIA 5 1/2 FT HIGH  
D. FIR STUMP WITH A FULLY  
HEALED BLAZE, BEARS S 67 1/2° W  
39.4 FT (REC. S 64 1/2° W, 39.4 FT)  
(1948)

NEW

22" DIA. W. OAK DOUBLE BLAZED  
AND SCRIBED "NW DLC 38 CS BT"  
BEARS N 52 1/2° W, 33.2 FT

22" DIA. W. OAK DOUBLE BLAZED  
AND SCRIBED "NW DLC 38 CS BT"  
BEARS N 4 1/2° E, 89.8 FT

15" DIA. D. FIR DOUBLE BLAZED  
AND SCRIBED "NW DLC 38 CS BT"  
BEARS N 38 1/2° E, 136.3 FT

COMPASS DEC. 17 1/2° E