

1-28-02

FILED FEB 6 2002

T255 RAW SECT 7 SE COR DCC 46
FRANZALL SMITH, STEPHEN J FLAUSÉ
FD 1956 DCSO BRASS CAP/IRON PIPE,
4" BELOW GROUND, LEANS 0.5 FT
SOUTH OF PLUMB. WE RE PLUMB
BC/IP.

NO BT'S FOUND
SE CORNER OF CHURCH BEARS
N 71° W, 66.7 FT (1965 REC.
N 42 1/2° W, 66.2 FT) (1968 REC. N 38 1/2° W,
66.2 FT)

A CHECK WAS MADE TO THE
1979 DCSO STATE PLANE COORD.
TIE. BACK SIGHT PLAT B, SET
UP ON FAIR OAKS & TURNED RT
WAS OBSERVED AS 259° 43' 46",
417.66 FT (REC PER CS 60/30
259° 46' 32", 417.67 FT) I ATTRIBUTE
SMALL ERROR TO THE PLUMBNESS
OF THE BC/IP

1929 1/2" IRON PIPE IN CEMETERY
BEARS N 81 1/4° W, 240.9 FT (CS 37/13
REC. N 82 1/4° W, 242.7 FT)

1992 5/8" IRON ROD BEARS
N 82 1/4° W, 230.8 FT (M 116-9 REC
N 84 1/4° W, 230.0 FT) IN E-W FENCE LINE
C.S. File No. 66/32-12

1-28-02
No. 332

1" O.D. IRON PIPE PROTRUDES
8" OUT OF GROUND BEARS N1°E,
104.5 FT

SOUTH EAST CORNER OF RED
BRICK CHIMNEY AT REC. HALL
HOUSE #866, BEARS N40½°E,
60.0 FT.

COMPASS DECL. 17½°E

PLSS #'S

037030

INT NW COR DLC 37

046020

SE COR DLC 46