

PI # 039010

6-13-92 FILED JUN 26 2002

T235 REW NW COR DLC 39

RANDALL W SMITH STEPHEN J FLAUSK

FA 1965 DCSO BRASS CAP/
IRON PIPE. PROTRUDES 7" OUT

OF GROUND TOP OF CAP BENT

6" SOUTH WEST OF PLUMB

- FENCE CORNER IS 3 FT

SW OF RC/1P.

24" NOW DOWN A ROTTED OAK

BEARS S 73° E, 112.5 FT (1921)

24" NOW 3" DIA W. OAK SCAR

NOT VISIBLE, BEARS S 14° E,

104.5 FT (1921)

DCSO RC/1P STRAIGHTENED SET

BACK AT PLUMB POSITION PROTRUDES

5" OUT OF GROUND.

NEW

- 20" DIA. MAPLE DOUBLE BLAZED AND

SCRIBED "NW DLC 39 CS BT"

BEARS S 82° E, 119.7 FT

- 18" DIA. W. OAK DOUBLE BLAZED AND

SCRIBED "NW DLC 39 CS BT"

BEARS N 87° E, 153.7 FT

COMPASS DECL 17 1/2° E

(ON BACK)

U.S. FILE NO

66/39-8

P1 #700600

T235

R	51		56	R
8	<hr/>			7
W	512		57	W

FOUND DIC

6-13-02