

PI # 050020

FILED JUL 29 2002

7-22-02

NNW COR DLC 50

T235 127W

SW COR DLC 51

FD 1965 DCSO BRASS CAP

IRON PIPE SET IN CONCRETE
AT 3WAY FENCE CORNER
PROTRUDES 4" OUT OF GROUND
STAMPING ON CAP ORIENTATED
SE.

- 10" NOW 23" O/A BIRCH WITH
A FULLY HEALED BLAZE, BEARS
S77°W, 19.8 FT (REC S72°W
14.8 FT) (1905)

- 8" NOW DOUBLE TRUNKED W. OAK
WITH A FULLY HEALED BLAZE
ON SOUTHERLY 16" DIA TRUNK
CENTER OF SCRIBED TRUNK
BEARS N61°W, 16.4 FT
(REC N61°W, 15.8 FT) (1905)

- 10" NOW 10" DIA. W. OAK
WITH A FULLY HEALED DOUBLE
BLAZE BEARS N35°W, 20.8 FT
(REC N33°W, 20.8 FT. BRG
HITS BLAZE) 1965
OBE NOT FOUND

COMPASS OBECL 17 1/4° E

C.S. File No 66/34-15

J. L. DARLING CORP.
TACOMA WASH 1914

"Rite in the Rain"
WEATHERPROOF

No. 302