

11-18-02

FILE 5049010

FILED NOV 26 2002

T285 R7W NE COR DCC 49

RANDALL W SMITH STEPHEN J FLAISE

FP 1968 DCSO BRASS CAP /
IRON PIPE IN N-S FENCE
LINK PROTRUDES 9" OUT OF
GROUND.

OBT NOT FOUND

12" NOW TRIPPLE TRUNKED W. OAK
WITH A FULLY HEALED BLAZE
ON 16" DIA NELY TRUNK
CENTER OF SCRIBED TRUNK BEARS
S58Y2W, 15.0 FT (CRUC S55°W,
15.0 FT) (1922)

6" NOW 17" DIA. DOWN AND
ROTTING B. OAK. ROOT HOLE BEARS
N77Y2°E, 18.0 FT (1922)

7" NOW 8" DIA. W. OAK WITH
A FULLY HEALED BLAZE, BEARS
S48°E, 11.0 FT (1968)

NEW
9" DIA W. OAK DOUBLE BLAZED AND
SCRIBED "NE DCC 49 CS BT"
BEARS N26°W, 16.7 FT

(ON BACK)

C.S. File No 66/48-10

J.L. DARLING CORP.
TACOMA WASH. 98401

"Rite in the Rain"
WEATHERPROOF

No. 302

10" DIA. D. FIR DOUBLE BLAZED
AND SCRIBED "NEOLC 49CS BT"
BEARS N 84 1/2° E, 34.0 FT

COMPASS OULL, 17 1/2° E

(NOTE WE PREPARE THE CORNER
AS DETERMINED IN 1922 AND
RENEWED IN 1968 SEE RECORDS
FOR ~~1916~~ BT AND DIST
DISCREPANCIES)