

FILED

GOVERNMENT CORNER RESTORATION FORM

Date: 5/17/2005 By: X

This survey consists of:

Township 32S Range 6W Sec. 35 County DOUGLAS Map:

State OREGON Date 4-7-2005 No. 038010

Name: _____
Corner type: 67/10-20

Corner Designation

N NE COR. REDFIELD
DLC # 38

DOUGLAS COUNTY
SURVEYOR

- Condition Report Only
- Not Found
- Renewed
- Unrecorded
- Surveyed In
- Referenced Out

Previous Renewals FREAR 1942, BBI 1953

Monument(s) Found: (Condition and Source)

2" INSIDE DIA. IRON PIPE,
LEANS WSW APPROX. 4"
PROJECTS 12" ABOVE GROUND.

Accessories Found:

- 12" Now 15" DIA. W. OAK, HEALED BLAZES VISIBLE
BEARS S 86° W, 48.7 FT. (REC. N88°04'W, 48.7 FT) 1953 BT
- 12" Now 19" DIA. W. OAK, HEALED BLAZES VISIBLE
BEARS N 13 3/4° W, 92.6 FT. (REC. N12°06'W 92.6 FT.) 1953 BT
- 18" Now 36" DIA. W. OAK, HEALED BLAZE VISIBLE
BEARS S 80° W, 333.3 FT. (AGREES W/ 1856 REC.) OBT

C.S. File No 67/10-20

