

GOVERNMENT CORNER RESTORATION FORM

Date: 7-26-05 By: JC

This survey consists of:

Township 22 S Range 8 W Sec. 15 County DOUGLAS

Map: \_\_\_\_\_

State OR Date ~~4-19-05~~

No. 053030 Corner Rpt: 67/10-37

7-20-05

Corner Designation

DOUGLAS COUNTY  
SURVEYOR

INT. L CORNER JAMES MERRICK  
DLC № 53

- Condition Report Only
- Not Found
- Renewed
- Unrecorded
- Surveyed In
- Referenced Out

Previous Renewals \_\_\_\_\_

MONUMENT DETAIL

Monument(s) Found: (Condition and Source)

1/2" I.D. IRON PIPE WITH COUPLER  
ATTACHED TO TOP, PROJECTS  
FROM GROUND 3 FT.  
5 FT. STEEL FENCE POST  
ALONGSIDE - UNKNOWN ORIGIN -  
IRON PIPE APPEARS STABLE.

Accessories Found:

NO EVIDENCE OF ORIGINAL CORNER TREE OR BEARING  
TREES FOUND.

