

GOVERNMENT CORNER RESTORATION FORM

FILED

Township 235 Range 5W Sec. 9 County Douglas Date: 3/21/06 By: JC

This survey consists of:

State OR Date 3-14-06 No. 03704 Map: _____

Corner Designation

SE COR DLC 37

Narrative: _____
Corner Rpt: 67/14-8

- DOUGLAS COUNTY Surveyor
- Not a Surveyor
- Renewed
- Unrecorded
- Surveyed In
- Referenced Out

Previous Renewals _____

MONUMENT DETAIL

Monument(s) Found: (Condition and Source)

1 1/2" I.D. IRON PIPE (UNKNOWN ORIGIN)
NEXT TO FENCE POST WITH UNMARKED STONE
ON SOUTH EDGE. STONE MEASURES
APPROX. 6" X 6" X 12". IRON PIPE PROJECTS
10" FROM GROUND AND LEANS SLIGHTLY
TO THE WEST

Accessories Found:

ROOT HOLE OF FALLEN 30"+ DIA. W. OAK, CENTER ROTTED
OUT & TRUNK ON THE GROUND, FOUND NEAR REC. BEARING.
DIST. FIT VERY WELL. (REC 15" W. OAK; S 20° E, 359° FT.) O.B.T.

