

FILED SEP 26 2007

AUG. 29, 2007

GPS COB2911A

T. 245 R5W 500300

$$\begin{array}{r} 22 \overline{) 23} \\ 27 \overline{) 26} \end{array}$$

1960 BT'S TO NORTH ARE
INTACT. LAND HAS BEEN
CLEARED TO SOUTH TAKING BT'S

T. 245 R5W 540300 $\frac{23}{26}$

1960 BT TO NORTH IS INTACT
HAS BEEN CLEARED TO SOUTH

T 245 R5W 640300 $\frac{24}{25}$

FO OK AS PER
1989 RENEWAL.

D.C.S.O.

J. PIKE

S. FLAUSE

C.S. File No 67/24-15