

FILED

GOVERNMENT CORNER RESTORATION FORM

Date: 3/7/08 By: JC

Township 26S Range 6W Sec. 25 County DOUGLAS

This survey consists of:  
Map: \_\_\_\_\_

State OR Date FEB. 26, 2008 No. 044620

Narrative: \_\_\_\_\_  
Corner Rpt: 67/25-17

Corner Designation

SW COR DLG 44

DOUGLAS COUNTY

Condition Report Only

Not Found

Renewed

Unrecorded

Surveyed In

Referenced Out

MONUMENT DETAIL

Previous Renewals 1946, 1964

Monument(s) Found: (Condition and Source)

2" I.D. IRON PIPE, BURIED 13"  
BELOW GROUND SURFACE

Accessories Found:

- 36" B.OAK, NOW DOWN, CENTER IS ROTTED OUT, NO SCRIBE VISIBLE  
ROOT HOLE AGREES WELL W/REC (N15°W, 15.8 FT.) O.B.T.
- 10" NOW TRIPLE TRUNK W. OAK, MOST WESTERLY TRUNK STUBS  
FULLY HEALED DOUBLE BLAZE & IS 15" DIA. CENTER OF ROOT CROWN  
BEARS N16½°E, 34.5 FT. (AGREES W/REC.) 1964 BT
- 14" NOW 17" DIA. B.OAK, FULLY HEALED DOUBLE BLAZE  
BEARS N77°E, 71.3 FT. (REC. N78½°E, 71.3 FT.) 1964 BT

C.S. File No 67/25-17

