

GOVERNMENT CORNER RESTORATION FORM

FILED

Date: 2/25/2009 By: X

Township 23S Range 4W Sec. 14 County \_\_\_\_\_ This survey consists of:

State OK Date 2-5-2009 No. \_\_\_\_\_ Map: \_\_\_\_\_

Corner Designation

CN 1/16 S14

Non active: \_\_\_\_\_  
Corner Rpt: 67/28-15

DOUGLAS COUNTY

- Condition Report Only
- Not Found
- Renewed
- Unrecorded
- Surveyed In
- Referenced Out

Previous Renewals M113-42

MONUMENT DETAIL

Monument(s) Found: (Condition and Source)

2 1/2" BRASS CAP ON A 2" IRON PIPE PROTRUDES 3" OUT OF GROUND.

T 23 S R 4 W

N 1/16 | S 14

PLS 752  
1991

Accessories Found:

24" NOW 28" DIA. HEMLOCK WITH SCRIBING VISIBLE  
" N 1/16 S 14 BT " ON OPENED DOUBLE BLAZE  
RECORD N 66° E 12.5 FT GOES TO NAIL IN BASE. CENTER  
OF ROOT CROWN BEARS N 63° E 13.8 FT. 1991

NW BT TIP OUT RECORD N 37° W 17.1 HITS  
ROOT HOLE 1991

