

GOVERNMENT CORNER RESTORATION FORM

Date: 4/21/2009 By: SC

Township 29S Range 1W Sec. 22 County DOUGLAS This survey consists of: :

State OK Date 4-8-2009 No. _____ Map: _____ Narrative: _____

Corner Rpt: 67/28-27

Corner Designation

1/4 S 22/S 23

DOUGLAS COUNTY

Condition Report Only

Not Found

Renewed

Unrecorded

Surveyed In

Referenced Out

MONUMENT DETAIL

Previous Renewals 1969 #26

Monument(s) Found: (Condition and Source)

2 1/2" DIA. BRASS CAP ON A
1 1/2" O.D. IRON PIPE, PROTRUDES
10" OUT OF GROUND (1969)

COUNTY SURVEYORS OFFICE
T 29S R 1W

1/4 S 22/S 23
1969

Accessories Found:

18" NOW 18" DIA 3 FT HIGH BURNED AND ROTTING
STUMP WITH AXE MARKS BEARS S 30° E, 35.6 FT
OBJ

3/4" I.R. 15 FT NORTH 1969

5/8" I.R. 25 FT NORTH 1969

1969 42" SE BT NOT FOUND. WE OPENED A 36"
D. FIR THAT HAD THE 1969 BT TAG ON E'LY TRUNK
NO SCRIBING FOUND. THIS TREE IS S 42° E 178.5 FT
FROM CORNER (1969 BT RECORD S 42° E 178.0 FT). I HAVE
NO IDEA WHERE THE 1969 TREE WAS LOCATED, NO EVIDENCE
OF A 42" D. FIR IS FOUND AT OR NEAR RECORD.

