

GOVERNMENT CORNER RESTORATION FORM

FILED

Date: 10/12/09 By: JC

Township 29S Range 5W Sec. 7

County DOUGLAS

This survey consists of:

State OK

Date 10-12-09

No.

Map:

Narrative:

Corner Rpt: CS 67/28-39

Corner Designation

1/4 57 | 58

DOUGLAS COUNTY

Condition: Submerged Part Only

Not Found

Renewed

Unrecorded

Surveyed In

Referenced Out

MONUMENT DETAIL

Previous Renewals 1926, 1962

Monument(s) Found: (Condition and Source)

2 1/2" BRASS CAP ON A 1 1/2" O.D.
IRON PIPE EXTENDS 18" OUT
OF GROUND: 1962

COUNTY SURVEYORS OFFICE
T29S R5W

1/4 57 | 58

1962

Accessories Found:

NO OBJECTS FOUND

15" NOW ROOT HOLE, BEARS N60°W 27.4 FT 1926

8" NOW 8" DIA DOWN W. OAK WITH A PARTIALLY HEALED
BLAZE AND ILLEGIBLE SCRIBING VISIBLE, ROOT HOLE
BEARS N42°E, 18.2 FT. 1962

C.S. File No 67/28-39

