

GOVERNMENT CORNER RESTORATION FORM

Date: 3/17/2011 By: JC

This survey consists of:

Township 29S Range 6W Sec. \_\_\_\_\_ County DOUGLAS Map: \_\_\_\_\_

State OREGON Date FEB. 24, 2011 No. 042040 Narrative: \_\_\_\_\_  
Corner Rpt: CS 67/33-10

Corner Designation

SSE  
DLC 42

DOUGLAS COUNTY  
SURVEYOR

Condition Report Only

Not Found

Renewed

Unrecorded

Surveyed In

Referenced Out

MONUMENT DETAIL

Previous Renewals 1919, 1965

Monument(s) Found: (Condition and Source)

FROM 1919 FREAR RENEWAL A 3/4 INCH  
IRON ROD FIRMLY SET AND PROTRUDING  
2 INCHES ABOVE GROUND

N/A

Accessories Found:

REMAINS OF THE ORIGINAL BEARING TREE.  
A W. OAK 16" DIA. NOW A 2 1/2 FOOT TALL 36 INCH DIAMETER WHITE OAK STUMP  
WHICH IS NOW BARKLESS AND HAS A ROTTEN CENTER WITH NO FACE OR SCRIBING  
REMAINING; BEARS N 41° W, 99° FEET DISTANT (AS PER RECORD)

FREAR RENEWAL TREE GONE.

FROM THE 1965 DCSD RENEWAL THE ONE NEW B.T. IS FOUND  
A 4° W. OAK NOW A 16 INCH D.B.H. WHITE OAK WITH NO EVIDENT BLAZING;  
BEARS S 27 1/2° W, 34 1/2 FEET DISTANT (RECORD S 25° W, 34 1/2 FT)

