

GOVERNMENT CORNER RESTORATION FORM

Township 265 Range 3W Sec. 13 County DOUGLAS

State OREGON Date APRIL 1, 2011 No. 640400

Corner Designation

1/4 513
524

- Condition Report Only
- Not Found
- Renewed
- Unrecorded
- Surveyed In
- Referenced Out

MONUMENT DETAIL

Previous Renewals 1960, 1965

Monument(s) Found: (Condition and Source)

FROM THE 1965 RENEWAL A 1 INCH INSIDE DIAMETER MONEL PIPE IS FIRMLY SET AND PROTRUDES 4 INCHES ABOVE THE GROUND.

N/A

WE DO NOT FIND THE 1960 MONUMENT

FILED

Date: 4-6-2011 By: JC

This survey consists of:

Map: _____

Narrative: _____

Corner Rpt: CS 67/33-25

DOUGLAS COUNTY SURVEYOR

Accessories Found:

THE REMAINS OF 2 BEARING TREES ORIGINALLY MARKED IN THE 1960 RENEWAL AND THEN REDESCRIBED IN THE 1965 RENEWAL.

AS DESCRIBED IN THE 1965 RENEWAL A 48" I. CEDAR NOW 44 INCH DIAMETER, 3 1/2 FOOT TALL, BARKLESS AND ROTTED INCENSE CEDAR STUMP WITH A "W" NAIL ON ITS FACE (NO OTHER MARKINGS FOUND); BEARS N84°E 35 1/2 FEET TO CENTER OF ROOT CROWN (RECORD N84°E, 33 1/2 FT. (THIS DISTANCE IS TO "W" NAIL)).

AS DESCRIBED IN THE 1965 RENEWAL A 30" FIR NOW A 36 INCH DIAMETER 2 FOOT TALL BARKLESS AND ROTTED FIR STUMP WITH NO "W" NAIL IN POSSIBLE FACE; BEARS N34°W, 27 1/2 FEET TO C.R.C. (RECORD N34°W, 25 1/2 FT. (THIS DISTANCE IS TO FACE OF STUMP)).

