

GOVERNMENT CORNER RESTORATION FORM

Date: 6/19/2012 By: J

This survey consists of:

Township 32 Range 09 Sec. 02

County DOUGLAS

State OREGON Date 3/28/11

No. 541700 CS 67/36-13

Corner Designation

T32S R09W AP SEC 02

DOUGLAS COUNTY

- Condition Report Only
- Not Found
- Renewed
- Unrecorded
- Surveyed In
- Referenced Out

Previous Renewals 1916, 1967

Monument(s) Found: (Condition and Source)

1883 - 18" FIR MARKED "45" ON NORTH FACE. THEN MARKINGS DESTROYED IN 1916 AND RESCRIBED "AP" ON NORTH FACE. NOW 23" D. FIR WITH FULLY HEALED SINGLE BLAZE ON NORTH SIDE.

1967 - 3/4" x 30" IRON ROD PROTRUDING 10" ABOVE GROUND BEARS N19°E, 12" FROM CENTER OF ROOT CROWN OF THE TREE MENTIONED ABOVE (RECORD IS "SET ON NORTH SIDE").

CENTER OF ROOT CROWN OF AP TREE BEARS S89 1/2°E, 34.0 FT. (1916 RECORD S89 1/2°E, 35.0 FT.) FROM N 1/4 COR. T32S R09W SEC 2 ONLY

Accessories Found:

1883 - A 24" FIR, NOW A 33" D. FIR WITH FULLY HEALED SINGLE BLAZE, FULLY HEALED HIGH LINE BLAZE, AND TIMBER CRUISER MARKS; BEARS S77°E, 9' 20" (AS RECORDED IN 1916)
A 30" FIR, NOW A 35" D. FIR WITH FULLY HEALED SINGLE BLAZE AND FULLY HEALED HIGH LINE BLAZE; BEARS S87°W, 9' 20" FT. (AS RECORDED IN 1916)

