

Fd OK

TOWNSHIP 30 RANGE 06 POINT IDENTIFIER # 600500

PRIMARY CORNER DESCRIPTION Sec. Cor. for 11, 12, 13 and 14

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

Bruce Shaner - For: Roseburg Resources Co. - June 2002 - M137-44 & C.S. File 65/44-6 L

Found - 1 1/2" dia., iron pipe & 7/8" iron rod alongside with mangled USBLM buried alongside, from which a:

- 30" W.Oak, face overgrown, bears S.17 1/2°W., 58.1 ft.
- 30" Maple, face overgrown, bears N.35°E., 138.6 ft.
- 32" W.Oak, face overgrown, bears S.72°E., 174.2 ft.
- 10" B.Oak, face overgrown, bears N.83°W., 16.7 ft.

Set - 3/4"x40" iron rod w/a 2 1/2" Alum cap, flush w/ground, over 1 1/2" iron pipe & 7.8" iron rod, marked:

ROSEBURG RESOURCES CO.

T30S R6W

S 11 | S 12

S 14 | S 13

RLS 430 2002.

6 ft. steel fence post bears North 1.0 ft.

Note - Corner lies North about 60 ft. from E-W access road (rocked)

Fd. BC by G. Lang, 5/2011 - M162-47

FOUND OK
11/4/19

DCSO
SJF AND JL

NW 10" OAK GONE (BURN PILE AT B & D)
STEEL FENCE POST GONE

LAT: 42.97037648

LONG: -123.3664888

FILED
Date: 12/18/2019 By: JC

This survey consists of:

Map: _____

Narrative: _____

Corner Rpt: CS 67/46-8

DOUGLAS COUNTY
SURVEYOR

C.S. FILE 67/46-8