

GOVERNMENT CORNER RESTORATION FORM

FILED

TOWNSHIP 26S RANGE 2W SEC. 29 PLSS # 200200

Date: 11/18/2021 By: JC  
This survey consists of:

DOUGLAS COUNTY OREGON

DATE 5-4-21

Map: \_\_\_\_\_

Narrative: \_\_\_\_\_

Corner Rpt: CS67/51-4

Corner Designation

See Cor 30/29  
31/32

DOUGLAS COUNTY  
SURVEYOR

Previous Renewals DCSD 1981 CS 61/27-45

Monument(s) Found: (Condition and Source)

- Condition Report
- Not Found
- Renewed
- Unrecorded
- Surveyed In

MONUMENT DETAIL

2 1/2" Alum Cap on 3/4" Iron Pipe  
By Shrum 1963 No Record

US PC Property Cor  
T26S R2W

DCSD 1981 CS 61/27-45  
Edwards 2010 M 160-76  
BLM Resurvey 2011 Vol  
5B pg 22933  
DCSD 2020 CS 67/46-38

30/29  
31/32  
P.E 4287  
1963

Accessories Found

ORIG. 1908 BEARING TREES

A. Root Hole S70°E 11.9 FT with fallen & decayed Fir  
Lying uphill

27" Cedar S30°W 13.9 FT GOOD SCAR

24 SAWED Fir Stump N19°W 18.6 FT GOOD SCAR

References by BLM 2011

5/8" Iron Rod with Alum Cap N72°45'42"E 81.33 FT  
MARKED RM T26S R2W 81.3 FT TO COR 29 2011

5/8" Iron Rod with Alum. Cap S34°18'07"E 75.46 FT  
MARKED RM T26S R2W 75.5 FT. TO COR 532 2011

5/8" Iron Rod with Alum. Cap N51°21'50"W 30.12 FT  
MARKED RM T26S R2W 30.1 FT TO COR 530 2011

All Caps HAVE ARROWS POINTING TO CORNER

Steel Fence Post 2' East

Monument Set (Procedure and Description)

MONUMENT DETAIL

\_\_\_\_\_
\_\_\_\_\_
\_\_\_\_\_
\_\_\_\_\_
\_\_\_\_\_
\_\_\_\_\_

New Accessories

\_\_\_\_\_
LAT. 43°16' 17.91" N
LONG. 122° 58' 14.91" W
\_\_\_\_\_
\_\_\_\_\_
\_\_\_\_\_
\_\_\_\_\_
\_\_\_\_\_
\_\_\_\_\_
\_\_\_\_\_
\_\_\_\_\_
\_\_\_\_\_
\_\_\_\_\_

Sketch of Monument, Accessories, and General Area

Location & Comments

AREA BURNT by ARCHIE FIRE
9-2020

CORNER IS 40' N. OF
ROAD & 20' WEST OF
ROAD TO ROCK QUARRY

RE TAG AND REFLAG
ACCESSORIES AFTER
FIRE

Comp. Decline. 14 1/2° E

Agency DCSD

Party Chief S. FIANSE

Note keeper

Witnesses J. LORSUNG

REGISTERED
PROFESSIONAL
LAND SURVEYOR

Ronald A. Quimby

OREGON
JULY 14, 1978
RONALD A. QUIMBY
1654

Expires: 12/31/2022

CS67151-4

TOWNSHIP 26 RANGE 02 POINT IDENTIFIER # 200200

PRIMARY CORNER DESCRIPTION Cor. Secs. 29, 30, 31, & 32

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GLO survey by Wm. N Gibb, Deputy Surveyor, under contract No. 783, dated Dec. 3, 1908 - (DCSO records Vol. 10 Page(s) 4242)

-----  
Set granite stone, 8x10x14", 10" in the ground for cor. secs. 29, 30, 31, & 32, marked with 5 notches on E & 1 notch on S edge, from which

A fir, 10" dia. bears N.66°E. 25 lks. mkd: T26S R2W S29 BT

A fir, 12" dia. bears S.7°E., 18 lks. mkd: T26S R2W S32 BT

A cedar, 20" dia., bears S.38°W., 21 lks., mkd: T26S R2W S31 BT

A fir, 14" dia. bears N.9°W., 28 lks. mkd: T26S R2W S30 BT

Douglas Co. Surveyors Office - Gregory E. Quibell, Deputy - Debbie Stewart - Sept. 17, 1981 - C.S. File 61/27-45

-----  
Found - 2½" Alum Cap on a ¾" I. Pipe (not of record), firmly set, protruding 6" out of a small mound of Stone. marked: US PC Property Cor T26S R2W 30 29 31 32 PE 4287 1963 Do not disturb. (PE 4287 was Thomas Shrum, DCSO JC 1/3/2008)

No trace of orig stone.

BTs - 15" Fir blow down (orig 10"), with well healed blaze bears N.66°E., 16.5 ft. to stump hole.

14" Fir blow down (orig. 12"), with well healed blaze bears S.7°E., 11.9 ft. to stump hole.

23" Cedar (orig. 20"), alive with well healed blaze, bears S.38°W., 13.9 ft.

23" Fir (orig. 14") with well healed blaze bears N.7°W., 19.2 ft. (Rec. N.9°W., 18.5 ft.)

New BTs- 10" cedar scribed "T26S R2W S29 CS BT" in double blaze, bears N.75°E., 40.1 ft.

9" cedar scribed "T26S R2W S32 CS BT" in double blaze, bears S.3°E., 12.7 ft.

Note - Corner is North 40 ft. of road centerline.

Fd. Shrum's cap & 3 BTs. Sets 6' steel post 2' east: By D. Edwards, 6/2010 - M160-76

BLM Dependent Resurvey by Kenneth W. Saveland, Cadastral Surveyor, under Group No. 2331, Surveyed April/Oct. 2011 - (DCSO records Vol. 58 Page(s) 22933)

-----  
The cor. of secs. 29, 30, 31, & 32, perpetuated by person(s) unknown, subsequently perpetuated by Quibell, in 1981, monumented with an iron post, 1" dia., firmly set, projecting 4" above a collar of stone, with aluminum cap (properly) mkd. from which the remains of original BTs  
continued next page

CS 67/51-4

TOWNSHIP 26 RANGE 02 POINT IDENTIFIER # 200200

PRIMARY CORNER DESCRIPTION Cor. Secs. 29, 30, 31, & 32

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

A roothole, bears S.7°E., 11.9 ft., with a fallen, decayed fir snag, size indeterminate, lying uphill, with no marks visible.

A cedar, 27" dia., bears S.38°W., 13.9 ft., with a healed blaze.

A sawed fir stump, 26" dia., bears N.9°W., 18.5 ft., with a healed blaze.

and a bearing tree mkd. by Quibell

A cedar, 12" dia., bears N.75¼°E., 40.5 ft., with fragmentary scribe marks visible on partially healed double blazes.

and new accessories

A rebar, 30". long, 5/8" dia., driven 29". in the ground for a reference monument, bears N.72°45'42"E., 81.33 ft., with an aluminum cap mkd. RM T26S R2W 81.3 FT TO COR S29 2011, and an arrow pointing to the cor.

A rebar, 30". long, 5/8" dia., driven 29". in the ground for a reference monument, bears S.34°18'07"E., 75.46 ft., with an aluminum cap mkd. RM T26S R2W 75.5 FT TO COR S32 2011, and an arrow pointing to the cor.

A rebar, 30". long, 5/8" dia., 29". in the ground for a reference monument, bears N.51°21'50"W, 30.12 ft., with an aluminum cap mkd. RM T26S R2W 30.1 FT TO COR S30 2011, and an arrow pointing to the cor.

Corner is located 40 ft. N. of a gravel road, 13 ft. wide, bears N.80°E. and S.80°W, and further located 20 ft. W. of the gravel access road of a rock quarry, 12 ft. wide, bears N.35°E. and S.35°W.

Latitude: ~~43°16'17.874"N~~ 1983 (CORS 96) *JUST SHOWING WE DISAGREE DONT HAVE TO CROSS OUT*  
Longitude: ~~122°58'14.858"W~~

Douglas Co. Surveyors Office - Crew: Stephen J Flause & Jeff Lorsung - 8/27/2020 - C.S. File 67/46-38

Found OK *43°16'17.91"* *-122°58'14.91"*  
Quibell's cedar (10" in 1981) / gone - road work  
Lat: ~~43.271636899~~ Long: ~~122.97080855~~  
~~10/2020 Still ok after fire~~ *DELETE THIS*

*MAY 4, 2021*  
*IN FIRE RETAG AND REFLAG REF.S*

*CS 67/51-4*