

TOWNSHIP 24 RANGE 02 POINT IDENTIFIER # 540100

FILED

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Sec. 35: & 2, T25-2

Date: 12/14/2023 By: X

Alias _____	Description _____	This survey consists of:
Alias _____	Description _____	Map: _____
Alias _____	Description _____	Narrative: _____
Alias _____	Description _____	Corner Rpt: <u>CG 67/57-17</u>

DOUGLAS COUNTY SURVEYOR

GLO survey by John A. McQuinn, Deputy Surveyor, under Contract #466, dated April 5, 1883 (DCSO records Vol. 7 Page(s) 2868)

Set post 3 ft. long, 3" sq., 24" in ground for 1/4 sec. cor. mkd. 1/4 S on N. face, from which

A Maple 20" dia., bears N.13°W., 25 lks. dist. mkd. 1/4 S BT

A Fir 40" dia., bears S.16°E., 38 lks. dist. mkd. 1/4 S BT.

BLM resurvey by Levi E. Tallett and C. Albert White, Cadastral Surveyors, under Group #294, Surveyed May 1951/Aug. 1963 - (DCSO records Vol. 32 Page(s) 13278)

"The intermediate corners along this line which were established by McQuinn formerly referred only to T. 24 S., R. 2 W. The purported retracement of the south boundary of sec. 31 and the reported establishment of closing corners on the boundary by Hezekiah Johnson in 1900 **having proved to be fictitious**, the McQuinn corners except for the south 1/4 sec. cor. of sec.31 and the south 1/4 sec. cor. of sec. 36, are changed in 1963 to corners of maximum control in order to provide a basis for Consent Decree "Civil No. 60-135, Oregon."

Point for the 1/4 sec. cor., at proportionate distance; there is no remaining evidence of the original corner. This now becomes the 1/4 sec. cor. of secs. 2 and 35.

Set an iron post, 28" long, 2 1/2" dia., 24" in the ground, with brass cap mkd:

1/4 $\frac{S\ 35}{S\ 2}$
1951

from which bearing trees mkd. in 1963:

A Hemlock 11" dia., bears N.33 1/4°E., 101 lks. dist. mkd. 1/4 S35 BT.

A Fir 11" dia., bears S.19 3/4°W., 82 lks. dist. mkd. 1/4 S2 BT.

GPS LOCATION FALL'S IN A LARGE LOGGED FLAT WITH NEW ROAD CONSTRUCTION. SEARCHED WITH MULTIPLE GPS ~~TIES~~ TIES & FOUND NO EVIDENCE.