

NOT FOUND 11/14/23

TOWNSHIP 24 RANGE 03 POINT IDENTIFIER # 340200

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 28 & 33

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GLO survey by L.H. Wheeler under Contract No. 467 dated April 7, 1883 (DCSO records Vol. 7 Page(s) 2999)

-----

Set hemlock post 3 ft. long, 3" sq., 24" in the ground for 1/4 sec. cor. marked 1/4 sec. cor. mkd. 1/4 S on N face from which  
 A hemlock, 10" dia., bears N.5°E., 11 lks., mkd: 1/4 S BT.  
 A hemlock, 24" dia., bears S.15°W., 18 lks., mkd: 1/4 S BT.

> S 11° W, 19'

Douglas Co. Surveyors Office - Vernon "Ray" Tracy -9/1967 - C.S. File 54/27

-----

Reported as not found.  
 Corner probably destroyed by old logging ✓

SEARCH FOR USING GIS AND GPS INFORMATION  
 FIND EVIDENCE OF OLD LOGGING SKID RD.  
 NO HEMLOCK STUMPS IN AREA.

N89°40'W  
40.16/80.32

43.44536  
123.06112

FILED  
 Date: 12/4/2023 By: SC  
 This survey consists of:  
 Map: \_\_\_\_\_  
 Narrative: \_\_\_\_\_  
 Corner Rpt: CS 67/57-20  
 DOUGLAS COUNTY  
 SURVEYOR

C.S. FILE 67/57-20