

TOWNSHIP 32 S RANGE 9 W SEC. 12

PLSS # 122512

Date: 6-19-25 By: KE

This survey consists of:
Map: _____
Narrative: _____
Corner Rpt: CS 67110-44

DOUGLAS COUNTY OREGON

DATE 6-18-25

DOUGLAS COUNTY
SURVEYOR

Corner Designation

T 32-9 SEC COR. S12 / S13 only

Monument(s) Found: (Condition and Source)

2 1/2" GLD BRASS CAP
proj 15" set solid

- Condition report
- Not Found
- Renewed
- Unrecorded
- Surveyed In

Previous Renewals

GLD Resurvey 1916 Vol
21 pg 8845-46
DCSO 1967 CS 54/44-41

MONUMENT DETAIL

T 32 S
S12 / S13
R 9 W
1917

Accessories Found

28" D. FIR N 3 1/4° W 126.7 FT (Dist. Not
Checked Trees on Line) Shows Good
SCAR
29" D. Fir S 62° W 15.0 FT Fully Healed
Double BLAZE ADD 3 1/2" MAG Nail RIGHT
Side Center

New Accessories

5" D. FIR S 6 1/2° W 5.7 FT Scribed
"X" BT ON Double BLAZE

10" CHINGUAPIA N 73° W 24.0 FT Scribed
T32S R9W S12 BT ON Double BLAZE

BOTH TREES HAVE 3 1/2 MAG NAIL
RIGHT SIDE CENTER

Sketch of Monument, Accessories, and General Area

Location & Comments

MODERATE MILD S.E. Slope
IN old FIR, CHINGUAPIA
Regrowth

CORNER IS ON TOP
OF Ridge Approx
125 FT NORTH OF
GRAVEL ROAD

OCRS Cottage Grove - Canyonville
Zone Position
42° 47' 51. 23824 N
123° 41' 50. 45021

Comp. Decline. 14 1/2° E
Agency DCSO
Party Chief S. FRAUSE
Note keeper
Witnesses J. LORSHING



CS 67160-44 pg 2/3

TOWNSHIP 32 RANGE 03 POINT IDENTIFIER # 100512

PRIMARY CORNER DESCRIPTION Sec. Cor. for 12 & 13 only, T32-9

Alias _____ Description TRIMBLE GEOXYT POSITION
 Alias _____ Description 42° 47' 51.162" N
 Alias _____ Description 123° 41' 50.416" W
 Alias _____ Description _____
 Alias _____ Description OGRS CANYONVILLE COTTAGE GROVE POS.

42° 47' 51.23824" N
123° 41' 50.45021" W

GLO Resurvey by Fred Mensch and Gerald A. Sorrels, Surveyors under Special Instructions, Group #35, dated Dec. 22, 1916 - (DCSO records Vol. 21 Page(s) 8845-46)

Set an iron post 3 ft. long, 2" dia., 24" in the ground for cor. of secs. 12 and 13, with brass cap mkd. T32S

2 1/2" B.C.	S12
	S13
	R9W
	1917

PROT. 15" BUT SOLID

from which

A Fir 5" dia., bears S.20°W., 45 lks. dist. mkd. T32S R9W S13 BT.

A Fir 12" dia., bears N.3°30'W., 192 lks. dist. mkd. T32S R9W S12 BT.

Douglas Co. Surveyors Office - John M. Powell, and crew - June 1967 - C.S. File 54/44-41

RENEWED 6/18/25

Found ~~28"~~ 12" now ~~19"~~ D.Fir N.3 1/2°W., 126.7 ft., shows good scar.

NOT CHECKED, TREES ON LINE

No trace of SW. BT

1917 GLO brass cap, properly marked (SEE ABOVE)

New BT ~~29"~~ 9" D.Fir S.62°W., 15.0 ft. mkd. T32S R9W S13 CSBT FHDB

No other good trees closer. (NW quad) ADD 3 1/2" MAG NAIL R.S.C. Corner lies on top of ridge, approx. 260 ft. N. of ~~deep~~ road.

175 GRAVEL

NEW REF'S

3 1/2" MAG-NAIL R.S.C. ON BOTH NEW B.T.S

5" DIA. D. FIR SCRIBED "X" "BT" ON HIGH-LOW BLAZE; BEARS S 6 1/2° W, 52 FT.

10" DIA. CHINQUAPIN SCRIBED "T32S R9W S12" "BT" ON DBL. BLZ, BEARS N 73° W, 24° FT.

MONUMENT ON MILD SE SLOPE IN OLD FIR, CHINQUAPIN REGROWTH.

MINI GIS
42.79753
123.69734