

6-24-2025
8/25/25 KC
CS 67/61-7

TOWNSHIP 26 RANGE 03 POINT IDENTIFIER # 300400

PRIMARY CORNER DESCRIPTION Sec Cor for 16, 17, 20 & 21

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

Rotten Fir stump N.68°E., 22.4 ft. (34 lks., not 24 lks.) Good scribing visible on previously opened face.

The above BTs are all trees mkd. by Eppstein in 1928.

36" Fir stump fits approx. location for Germond's NE tree, no marks found on stump.

No original bearing trees found.

Set Brass cap at cor. mkd: County Surveyors T26S R3W S17|S18
Office, 1963 S20|S21

New BTs - 14" D.Fir N.72½°E., 132.6 ft. mkd: T26S R3W S16 CSBT
22" Madrone N.32½°W., 300.0 ft. mkd: T26S R3W S17 CS BT.

No other trees available. Corner lies in fence corner

Found OK, Glenn Baughman, April, 1988, M 106-1
Found OK, Glenn Baughman, March 1992, M 114-72
Found OK by Mike Schulze July 2009, M159-61

Douglas Co. Surveyors Office - Crew: Stephen Flause & Jeff Lorsung- 2/3/2023 - C.S. File 67/55-37

Found - DCSO 2½" brass cap (properly mkd) on 1" I.D. I.Pipe up 14" in fence corner.
References not checked due to problem neighbor
14" D.Fir N.72½°E., 132.6 ft.
← 22" Madrone N.32½°W., 300.0 ft.

New - D.fir S.30°E., 12.9 ft. double blaze, scribed X BT, 3½" mag nail right side center.

Note - Area burnt 9/2020
Corner is in fence corner.
Compass decl. 14½°E.

OCRS Coordinate System Cottage Grove - Canyonville Zone
N 170669.667 E 234201.951

5/8" x 30, IR, 8 8, S 82° E

5/8" x 30, IR, 8 6, S 10° W

KNUCKED THE TAG OFF THE MADRONE
SO IT CAN BE REMOVED BY AN ARBORIST