

TOWNSHIP 22S RANGE 12W SEC. 22 PLSS # 440340

Date: 9/22/25 By: KE

DOUGLAS COUNTY OREGON

DATE 9-10-25

This survey consists of:

Map: _____

Narrative: _____

Corner Rpt: CS 07/01-24

DOUGLAS COUNTY SURVEYOR

Corner Designation

C'14 S 22

Monument(s) Found: (Condition and Source)

2 1/2" BRASS CAP ON

IRON PIPE

Condition report

Not Found

Renewed

Unrecorded

Surveyed In

Previous Renewals

Gould F.B. 53 pg 129

CS File 62/35

WARD 1981-1982 M 92-58

MONUMENT DETAIL

T22S R12W

C'14 S 22

1982

LS1091

Accessories Found

Nearly Rotted To Ground Alder stub
N 31° 30' W 5.4 FT

24" X 4 FT SAWN CEDAR STUMP S 73° E
18.4 FT Fully Healed Single BLAZE
Add 3 1/2" MAG NAIL RIGHT SIDE CENTER

Monument Set (Procedure and Description)

MONUMENT DETAIL

New Accessories

6" D. Fir EAST 9.5 FT Scribe X BT ON Double BLAZE

12" D. Fir S76°W 16.4 FT Scribed C'1/4 522 BT ON Double BLAZE

5/8" x 30" I. Rod with DCSO plastic CAP Proj 3" N43 1/2°W 56.7 FT IN ROAD Shoulder

Sketch of Monument, Accessories, and General Area

Location & Comments

OCES Cottage Grove Canyonville zone Location

MON 1/2 older Reprd 60 FT EAST of Logging ROAD

43°38'51.05276" N
124°06'50.82023 W

Comp. Decline. 14 1/2° E
Agency DCSO
Party Chief S. F. AUSE
Note keeper
Witnesses J. LORSUNG

CS 67/61-24

pg 2/3

REGISTERED PROFESSIONAL LAND SURVEYOR

Ronald A. Quimby

OREGON JULY 14, 1978 RONALD A. QUIMBY 1654

EXPIRES: 12/31/2026

TOWNSHIP 22 RANGE 12 POINT IDENTIFIER # 440340

PRIMARY CORNER DESCRIPTION Center 1/4 Cor. for Sec. 22

Alias _____	Description _____
Alias _____	Description <u>OCRS CANYONVILLE COTTAGE GROVE POSITION</u>
Alias _____	Description _____
Alias _____	Description <u>43°38'51.05270"N</u> <u>124°06'50.82023"W</u>

MINI GIS
43.64754
124.11419

A.N. Gould's Field Book #53 Page 129 - 1916 - (DCSO records, C.S. File 62/35)

Set Cedar for center Sect. 22
Hemlock 24" N.38°W., 32.0 ft.
Cedar 120", S.83½°W., 17.0 ft.
Cor. about 50 ft. from top of divide on North slope.

DECLINATION 14½°E

RENEWED 9/10/25

Survey by Robert B. Ward, Jr. - For: Champion International Corp. - Nov. 1981/June 1982 - M 92-58

"T225 R12W"
C1/4 S22

Set 2½" brass cap on 2½" x 30" I.P. with stamped "LS 1091"

1982 ✓

NEARLY ROTTEN TO
GROUND ALDER STUB
SAWN CEDAR STUMP

12" Alder ✓ bears N.31°30'W ✓ 5.4 ✓ ft. scribed C¼ S22 BT.
34" Cedar ✓ bears S.73°00'E ✓ 18.4 ✓ ft. scribed C¼ S22 BT. FH 5B
(TO NAIL) ADD 3½" MAG NAIL R.S.C.

NEW REFERENCES

A 6" DIAM. D. FIR SCRIBED "X" "BT" ON A HIGH-LOW BLAZE; BEARS EAST, 9⁵ FT. DIST.

A 12" DIAM. D. FIR SCRIBED "C1/4 S22" "BT" ON A DOUBLE BLZ; BEARS S76°W, 16⁴ FT. DIST.

A 5/8" x 30" I.R. / DCSO PLASTIC CAP I.R. IS SET PROT. 3 INCHES IN RD SHOULDER; BEARS N43½°W, 56⁷ FT. DIST.

MONUMENT IN OLDER REPROD. 60 FT. EAST FROM LOGGING ROAD.