

GOVERNMENT CORNER RESTORATION FORM

FILED

TOWNSHIP 24S RANGE 3W SEC. 34 PLSS # 500100

Date: 12/10/25 By: ke

This survey consists of:

DOUGLAS COUNTY OREGON

DATE 12-08-25

Map: _____

Narrative: _____

Corner Rpt: CS 67/01-49

Corner Designation

SEC COR $\frac{24S}{34 | 35}$
 $\frac{3 | 2}{25S}$

DOUGLAS COUNTY SURVEYOR

Monument(s) Found: (Condition and Source)

2 1/2" BLM BRASS CAP
proj 7"

___ Condition report

___ Not Found

Renewed

___ Unrecorded

___ Surveyed In

Previous Renewals

BLM Resurvey 1940 Vol 27 pg 11536-37

DCSO 1966 CS 54/27-131

Holt 1981 m 90-16

BLM Resurvey Vol 48 pg

18476-77

MONUMENT DETAIL

T24S R3W

534 | 535

53 | 52

T25S

1944

Accessories Found

Very Burched and Rotted 40" X 5 FT FIR

Stump N 33 1/4° E 52.1 FT

BURNED DEAD 30" R. Cedar 529° E 9.0 FT

(REG 4.6 FT) Tree Hollowed out

BURNED Rotted 23" X 7 FT VI. FIR 5049

S 48 1/2° W 40.3 FT Top of SCAR Visible

Burned to stub R. Cedar N 51 1/2° W 37.6 FT

BURNED - DEAD 28" D. FIR N 10° E 24.3 FT

BLAZE NOT Visible

27" X 6 FT R. Cedar Stump N 69° W 35.6 FT

BLAZE NOT Visible

Fence Post 10 FT North

Monument Set (Procedure and Description)

MONUMENT DETAIL

New Accessories

Sketch of Monument, Accessories, and General Area

Location & Comments

MON NEAR TOP OF moderate
 SW slope clearcut NW 1/4
 S.E Rest Burnt Trees

AREA BURNED
 9/2020

OCRS COORDINATE SYSTEM
 Cottage Grove - Canyonville zone

Comp. Decline. 14' 4" E
 Agency DLSD
 Party Chief S. F. HAUSE
 Note keeper
 Witnesses J. ZORSHAN

N 218706.541
 E 244919.842

CS 67161-49
 pg 24

REGISTERED
 PROFESSIONAL
 LAND SURVEYOR

Ronald A. Quimby

OREGON
 JULY 14, 1978
 RONALD A. QUIMBY
 1654

EXPIRES: 12/31/2026

TOWNSHIP 24 RANGE 03 POINT IDENTIFIER # 500100

PRIMARY CORNER DESCRIPTION Sec. Cor. for 34 & 35; 2 & 3 of T25-3

| | |
|-------------|-------------------|
| Alias _____ | Description _____ |
| Alias _____ | Description _____ |
| Alias _____ | Description _____ |
| Alias _____ | Description _____ |

Original - W. H. Byars, Under Contract #152 dated June 3, 1871 (DCSO records, Volume 7 Page 2945)

Set post cor. to secs. 2, 3, 34 and 35, from which

- A Fir 12" dia. bears N.60°E., 65 lks. dist.
- A Fir 72" dia. bears S.30°E., 50 lks. dist.
- A Fir 60" dia. bears S.10°W., 15 lks. dist.
- A Fir 96" dia. bears N.70°W., 34 lks. dist.

GLO Dependent Resurvey by Norman Price, Under Special Instructions dated April 5, 1940 (DCSO records, Vol.27 Pages 11536-37)

By proportional measurement, set an iron post, 3 ft. long 2" dia., 28" in the ground, for cor. of secs. 2, 3, 34 and 35, with brass cap mkd.

2 1/2" BC

| | | |
|------|---------|---|
| T 24 | S R 3 W | ✓ |
| S 34 | S 35 | |
| S 3 | S 2 | |
| T25S | | |
| 1944 | | |

PRDT 7"

1944 from which

- A Fir 60" dia., bears N.33¼°E., 79 lks. dist. mkd.
T 24 S R 3 W S35 BT.
- A Red Cedar 12" dia. bears S.29°E., 7 lks. dist., mkd.
T 25 S R 3 W S 2 BT.
- A Fir 6" dia. bears S.48½°W., 61 lks. dist. mkd. T 25 S R 3 W S 3 BT.
- A Red Cedar 8" dia., bears N.51½°W., 57 lks. dist., mkd. T 24 S R 3 W S34 BT.

DECLINATION 14 1/4° E

RENEWED 12/8/25

Douglas County Surveyors Office - Ray Tracy; Jack Heritage Sept. 1966 - C.S. File 54/27-131

SEE ABOVE

Found - 1944 GLO brass cap with steel fence post set alongside and bent over. Reset fence post alongside cap. *FNC, POST IS 10 FT NORTH*

VERY BURNED AND ROOTED 40" x 5 FT 60" Fir stump N.33¼°E., 52.1 ft., shows "T24S R3W S35 BT" scribe on unhealed blaze *BLAZE GONE*

BURNED DEAD 38" - 12" now 20" R.Cedar S.29°E., 4.6 ft. shows good scar. Rescribe "T25S R3W S2 CS BT" *TREE HOLLOWED OUT*

BURNED KOTTED 23" x 7 FT SNAG 6" now 16" W. Fir S.48½°W., 40.3 ft. 48" log lying against scar, only top of scar visible ✓

BURNED TO STUB IN GROUND 8" now 14" R.Cedar snag, N.51½°W., 37.6 ft., dead & burned, no scribes.

MORE FOUND B.T.s OVER

NEW REF. - 26" x 2 FT. TALL; 3 1/2" MAG NAIL SET IN TOP BEARS N51 1/2° W, 40 FT. DIST.

MONUMENT NEAR TOP OF MODERATE SW SLOPE LARGE CLEAR CUTS NW & SE REST BURNED TREES

CS 6714-49 pg 3/4

(Cont. next page)

TOWNSHIP 24 RANGE 03 POINT IDENTIFIER # 500100

PRIMARY CORNER DESCRIPTION Sec. Cor. for 34 & 35; 2 & 3 of T25-3

Alias _____ Description OCRS CANYONVILLE COTTAGE GROVE COORD.S
 Alias _____ Description _____
 Alias _____ Description 218706.541
 Alias _____ Description 2447919.842

BURNED DEAD

New BTs 28" D.Fir N.10°E, 24.3 ft. mkd. ~~T24S R3W S35 CS BT~~ ALZ NOT VIS
27" x 6 FT STUMP R.Cedar N.69°W, 35.6 ft. mkd. T24S R3W S34 CSBT " " "
 Corner lies on moderate west slope approx. 120 ft. W. of top of spur.

Found OK, Burton Holt, Dec. 1981, M 90-16
 Found and used, BLM Dependent Resurvey by Rogers, etal, Group #1386 - 1987-88 (DCSO records, Vol. 48 Pages 18476-77)

CS 67161-49 pg 4/42