

GIS  
R01222A


DOUGLAS COUNTY SURVEYOR'S OFFICE

Designation: B-172 Station: BUCK-5 T 27S R 4W S 20 1/4 SE

Date Set: ? Set by (Agency): DCPW

Date Recovered: 1-22-03 Recovered by: RUS SJF

- Found
- Not Found
- New
- Referenced
- Reset
- Destroyed



VERTICAL CONTROL

NGVD 29 Elevation: 741.44 Feet File # CS66/63  
 Precision: 3rd Agency: DCSO Project: 2007 Date: 2003  
 NAVD 88 Elevation: 744.99 Meters File # \_\_\_\_\_  
 Precision: CORPCON 6 Agency: \_\_\_\_\_ Project: \_\_\_\_\_ Date: \_\_\_\_\_  
NAVD 88

HORIZONTAL CONTROL - south zone

N _____	E _____	Datum/Adj.: <u>1927</u>	Precision: <u>GIS</u>
Lat: <u>43°12'19.7"</u>	Long: <u>123°11'15.1"</u>	Agency: <u>DCSO</u>	<u>CS 66/63</u> File # <u>R01222A</u> Date: <u>2003</u>
N _____	E _____	Datum/Adj.: _____	Precision: _____
Lat: _____	Long: _____	Agency: _____	File # _____ Date: _____
N _____	E _____	Datum/Adj.: _____	Precision: _____
Lat: _____	Long: _____	Agency: _____	File # _____ Date: _____
N _____	E _____	Datum/Adj.: _____	Precision: _____
Lat: _____	Long: _____	Agency: _____	File # _____ Date: _____

DESCRIPTION AND TO REACH

DCPW BRASS CAP AT SE CORNER  
OF CONCRETE BRIDGE W/  
STAMP "BUCK-5 2003"

FROM THE INTERSECTION OF  
DIXONVILLE RD (CO. RD #164)  
AND BUCKHORN RD (CO. RD #17)  
IN T27S R5W SEC. 24 AT  
DIXONVILLE PROCEEDED EASTWARD  
ALONG BUCKHORN ROAD 2.8 MILES  
TO INTERSECTION WITH STRADER  
RD (CO. RD #136) PROCEEDED  
NORTHERLY ALONG STRADER RD  
0.05 MILE TO MONUMENT ON  
RIGHT AT SE CORNER OF CONCRETE  
BRIDGE.

