


R041019A **DOUGLAS COUNTY SURVEYOR'S OFFICE**

Designation: B-182 Station: BEND-1 T 24S R 7W S 30 1/4 SE

Date Set: 2003 Set by (Agency): DCSO

Date Recovered: 4-10-03 Recovered by: RWS STF

- Found New Reset
- Not Found Referenced Destroyed



VERTICAL CONTROL

NGVD 29 Elevation: 307.19 Feet File # CS 67/2
 Precision: 3rd Agency: DCSO Project: 2007 Date: 2003
 NAVD 88 Elevation: 310.69 ^{FT} Meters File # _____
 Precision: CORPCON 6 Agency: _____ Project: _____ Date: _____
NAVD 88

HORIZONTAL CONTROL - south zone

N _____	E _____	Datum/Adj.: <u>1927</u>	Precision: <u>615</u>
Lat: <u>43° 27' 16.0"</u>	Long: <u>123° 33' 54.1"</u>	Agency: <u>DCSO</u>	<u>R041019A</u> File # <u>67/2</u> Date: <u>2003</u>
N _____	E _____	Datum/Adj.: _____	Precision: _____
Lat: _____	Long: _____	Agency: _____	File # _____ Date: _____
N _____	E _____	Datum/Adj.: _____	Precision: _____
Lat: _____	Long: _____	Agency: _____	File # _____ Date: _____
N _____	E _____	Datum/Adj.: _____	Precision: _____
Lat: _____	Long: _____	Agency: _____	File # _____ Date: _____

DESCRIPTION AND TO REACH

DCSO BRASS CAP STAMPED "BEND-1"
200.3" SET 8" DIA. CONCRETE FILLED
BELL TILE, SET FLUSH WITH
GROUND.
FROM THE INTERSECTION OF TYEE ROAD
(CO. RD #33) AND TYEE BRIDGE ACCESS
ROAD (BLM RD #25-7-5.1) IN T25S
R7W, SEC. 5 PROCEED NORTHERLY
ALONG TYEE ROAD 1.35 MILES TO
INDIAN BEND ROAD ON LEFT, PROCEED
NORTHERLY ON INDIAN BEND ROAD
0.25 MILES TO INTERSECTION
PROCEED NORTHERLY ALONG RIGHT
FORK 0.25 MILES TO MONUMENT
ON LEFT.

