

# Douglas County Geodetic Data Sheet


T 31 R 04 WS 27 A

Station: GR-4

Designation: G-087

Date Set: 1985 Set By (Agency): DCPW

Last Date Recovered: 11/27/1987



## VERTICAL CONTROL

NGVD 29 Elevation: 1,981.03 Feet

Precision: 3RD ORDER Agency: DCSO

CS File: 66023

Date: 2001

NAVD 88 Elevation: 1984.53 <sup>FEET</sup> <sub>Meters</sub>

Precision: CORPSCON 6 Agency:

CS File:

Date:

## HORIZONTAL CONTROL

OCS 27 Y(Northing): 443,114.75 X(Easting): 1,287,451.09 Lat

Long:

Precision: Agency: DCPW

CS File: 631361G

Date:

OCS 83 Y(Northing): X(Easting): Lat

Lat

Long:

Precision: Agency:

CS File:

Date:

OCS 83/91 Y(Northing): X(Easting): Lat

Lat

Long:

Precision: Agency:

CS File:

Date:

OCS 83/98 Y(Northing): X(Easting): Lat

Lat

Long:

Precision: Agency:

CS File:

Date:

Scaled Lat

Long:

### Description:

DCPW BRASS CAP SET IN CONCRETE

### Comments:

TAKE EXIT NO 88 FROM I-5 AND PROCEED EAST ON UPPER COW CR. RD; CO RD NO 36 TO MP 7.97. CAP IS LOCATED ON A 10FT HIGH CUT BANK APPROX 72 FT LEFT OF CENTERLINE STA 124+60 AND 86 FT. FROM PPL POWER POLE NO. E4613

Note: For further information contact the Douglas County Surveyors Office, Room 105A Douglas County Courthouse, Roseburg, OR 97470. Phone 440-4272 or Fax (541)957-8150. Douglas County Residents outside Roseburg calling area, dial toll free 1-800-224-1619.