


OFFICE OF THE  
DOUGLAS COUNTY SURVEYOR



H-092

Station: HEETER

T 22 S, R 6W, Sec 16


Date Set: 2000

Set By (Agency): DCSO

Date Recovered: 3-28-06

Recovered By: RWS SJF

- Found
- New
- Reset
- Not Found
- Referenced
- Destroyed



VERTICAL CONTROL NGVD 29

CORPSCON 6 NAVD 88 443.50 FT

Elevation: 440.03 NGS Line # \_\_\_\_\_ USGS Line # \_\_\_\_\_ OSHD Line # \_\_\_\_\_

Precision: 3rd Agency: DCSO Proj. # 66/38 Date: 2000

HORIZONTAL CONTROL

South Zone O.C.S. 27: Y(Northing) \_\_\_\_\_ X(Easting) \_\_\_\_\_

South Zone O.C.S. 83: Y(Northing) \_\_\_\_\_ X(Easting) \_\_\_\_\_

Precision: \_\_\_\_\_ Agency: \_\_\_\_\_ Proj. # \_\_\_\_\_ Date: \_\_\_\_\_

Approx. NAD 83 Geographic Position: Latitude 43° 13' 17.2" Longitude 123° 24' 30.6"

(27) 43° 13' 17.8" 123° 24' 26.3"

DESCRIPTION and TO REACH

DCSO DRILL CAP STAMPED "HEETER 2000"  
SET IN NORTH WEST CORNER OF CONCRETE  
DRIVEWAY

FROM THE INTERSECTION OF HARLAN ST AND  
TROST (CORP #273) IN T22S R6W SEC 16  
PROCEED WESTERLY APPROX 225 FT  
TO DRIVEWAY AND MONUMENT ON RIGHT.

Reference Marks:

