



OFFICE OF THE
DOUGLAS COUNTY SURVEYOR

Station: MADISON T 25 S, R 5 W , Sec 30
 Set By (Agency): OSHD
 Date Set: ?
 Recovered By RWS, SJF
 Date Recovered 5/9/89
 Recovered By _____
 Date Recovered _____
 Recovered By _____
 Date Recovered _____



M-066



VERTICAL CONTROL NGVD 29

Elevation: 502.294 NGS Line # _____ USGS Line # _____ OSHD Line # _____
 Precision: 2nd Agency: DCSO Proj. # 2007 Date: 1990

HORIZONTAL CONTROL


South Zone State Plane Coordinates: Y(Northing) _____ X(Easting) _____
 Precision: _____ Agency: _____ Proj. # _____ Date: _____
 Approximate Geographic Position: Latitude _____ Longitude _____

DESCRIPTION and TO REACH

SKETCH

An OSHD disk stamped "DCSO MADISON 1989"
set at northwest corner of concrete bridge curb.

Go to the intersection of State Hwy. 99
(Co.Rd.#388) and south Sutherlin access
road (exit 135) in T25S,R5W,Sec.30, proceed
southwesterly along access road approx.
200 ft. to monument on right.



Reference Marks:

Note: For further information, contact the Douglas County Surveyor's Office, Room 205 Douglas County Justice Building, Roseburg, OR 97470. Phone 440-4278. Douglas County residents outside the Roseburg calling area, dial toll free 1-800-452-0991.